

Submit 3 Copies
to Appropriate
District Office

District I

P.O. Box 1980, Hobbs, NM 88240

District II

P.O. Box 1980, Hobbs, NM 88240

District III

P.O. Box 1980, Hobbs, NM 88240

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONVERSATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO.	30 - 025 - 20301
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B1482

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit agreement Name STATE K
2. Name of Operator OXY USA INC.	8. Well No. 7
3. Address of Operator P.O. Box 50250 Midland, TX 79710	9. Pool name or Wildcat VACUUM YATES
4. Well Location Unit Letter <u>A</u> : <u>990</u> Feet From The <u>NORTH</u> Line and <u>330</u> Feet From The <u>EAST</u> Line Section <u>27</u> Township <u>17 S</u> Range <u>35 E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,936	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <u>PLUG BACK & RECOMPLETE</u> ☒

12. Describe Proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1103.

TD - 6291' PBTD - 3370' PERFS - 3039' - 3121

SEE OTHER SIDE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 01 16 92
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

ORIGINAL SIGNED BY WARY SEXTON
DISTRICT COORDINATOR

APPROVED BY WARY SEXTON TITLE DISTRICT COORDINATOR DATE JAN 22 '92

CONDITIONS OF APPROVAL, IF ANY:

3A Marista E

Attachment C-103
 OXY USA Inc.
 State K #7
 Sec 27 T17S R35E
 Lea County, New Mexico

MIRU PU, NDWH, NUBOP, POOH w/rods, pump, & tbg. RIH w/ bit, csg scraper on 2 7/8" tbg, tag @ 6205'. RIH w/ 5 1/2" CIBP's & set @ 6020' & 3390' w/ 2sx (20') cmt on top of both, new PBTD 3370'. Perf Yates w/ 2 SPF @ 3039,40,41,42,43,44,45,46,49,50,51,52,53,-54,66,67,68,69,70,71,72,88,89,90,91,92,93,98,99,3100,01,02,03,-04,05,06,07,08,09,10,14,15,16,17,18,19,20,3121', Total 96 holes. SITP-150#, RIH w/ tbg & pkr & set & 2957', test csg to 500#, held OK. Acidize Yates 3039'-3121' w/ 2400 gal 7 1/2% NeFe HCL acid. Swab trace oil in 3 hrs. Fraced Yates 3039'-3121' w/ 21000 gal 30# gel & 49000# 12/20 sand. SITP-1600#, swab & flow test well as follows:

<u>TEST</u>	<u>OIL</u>	<u>WATER</u>	<u>GAS</u>	<u>CHOKE</u>	<u>SITP</u>
2hr	0	35LW	*	open	1600
9hr	10	162LW	*	open	800
9hr	5	53LW	*	open	650
8hr	6	34LW	*	open	600
9hr	9	23LW	*	open	550
9hr	7	23LW	*	open	700
9hr	4	20LW	*	open	500

*good show of gas

SITP-450#, Rel pkr, POOH w/ 2 7/8" tbg, RIH w/ 2 3/8" tbg & set @ 3116', NDBOP, NUWH. RIH w/ 2"X1 1/2"X16' BHD pump on 3/4" rods, RDPU. Started well pumping to test tank @ 10.5 SPM w/ 74" stroke 12/17/91. Test well as follows:

<u>TEST</u>	<u>OIL</u>	<u>WATER</u>	<u>GAS</u>
24hr	0	208LW	---
24hr	8	18LW	---
24hr	10	16LW	---
24hr	15	9LW	---
24hr	16	3LW	---

On NMOCD potential test 12/22/91, pumped 13BO, 37.5°, 2BW, 52G, 4000GOR in 24 hrs.