

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>3D-D25-20305</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name <b>SMITH '5'</b>
2. Name of Operator <b>SOUTHLAND ROYALTY COMPANY</b>	8. Well No. <b># 2</b>
3. Address of Operator <b>P.O. Box 51810, Midland, TX 79710-1810</b>	9. Pool name or Wildcat <b>SCHARB BONE SPRINGS</b>
4. Well Location Unit Letter <b>O</b> : <b>660'</b> Feet From The <b>SOUTH</b> Line and <b>1980'</b> Feet From The <b>EAST</b> Line Section <b>5</b> Township <b>19S</b> Range <b>35E</b> NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3858 GR</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/10/93: MIRU. POOH W/RODS. RODS PARTED.  
11/11/93: NU BOP. POOH W/TBG. TIED ONTO RODS. COULD NOT UNSEAT PMP. BACKED OFF RODS. STRIPPED OUT OF HOLE.  
11/14/93: STRIPPED OUT OF HOLE W/REST TBG AND RODS. RIH W/CIBP ON WIRELINE. SET AT 9508. RD WIRELINE. ND BOP. WELDED ON PULL NIPPLE.  
11/15/93: RIH W/DMP BAILER. DMPED 35' CMT ON TOP CIBP. RIH W/JET CUTTER ON WIRELINE. CUT CSG AT 6600. POOH W/CSG. STUCK CSG. WORKED W/CSG AND WAS ABLE TO FREE PIPE. POOH W/2700 CSG.  
11/16/93: POOH W/RET CSG. NU BOP. RIH W/TBG TO 6650. PMPED 35 SXS CMT. POOH W/TBG. WOC 4 HRS. RIH. TAGGED PLUG AT 6543. PU TO 4600. PMPED 35 SXS. PU TO 4040. PMPED 35 SXS. POOH W/TBG. WOC  
11/17/93: RIH TO TAG SHOE PLUG. PLUG WAS NOT THERE. PMPED 35 SXS CMT AT 4040. POOH W/TBG. WOC 4 HRS. RIH. TAGGED SHOE PLUG AT 3820. RIH W/TBG TO 3020. PMPED 35 SXS CMT. POOH W/TBG. WELDED ON 8 5/8 5/8" PULL NIPPLE. RIH. CUT CSG AT 2080. PIPE WAS NOT LOOSE. PMPED 35 SXS AT 2080. POOH W/TBG.  
11/18/93: SHOT OFF 8 5/8" CSG AT 1200. WAS NOT LOOSE. SHOT OFF 8 5/8" CSG AT 900. WAS NOT LOOSE. RIH W/TBG TO 1250. SPOT 35 SXS CMT PU TO 950. SPOT 35 SXS. PERF AT 478. PMPED 150 SXS CMT CIRCULATED TO SURF. PMPED 30 SXS SURFACE PLUG. CUT OFF WH 3' BELOW SURFACE. INSTALLED P&A MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Williams TITLE PRODUCTION ASSISTANT DATE 11/22/93

TYPE OR PRINT NAME DONNA WILLIAMS

TELEPHONE NO. 915-688-6943

(This space for State Use)

APPROVED BY Camy W. Hill TITLE OIL & GAS INSPECTOR DATE 11/22/93

CONDITIONS OF APPROVAL, IF ANY: