

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-1
Effective 1-1-81

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
SHELL OIL COMPANY
3. Address of Operator
P. O. BOX 991, HOUSTON, TX 77001
4. Location of Well
UNIT LETTER <u>I</u> <u>2310</u> FEET FROM THE <u>south</u> LINE AND <u>660</u> FEET FROM
THE <u>east</u> LINE, SECTION <u>33</u> TOWNSHIP <u>17S</u> RANGE <u>35E</u> N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name
State <u>T</u>
9. Well No.
<u>9</u>
10. Field and Pool, or Wildcat
Vacuum-Glorieta
12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3948' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Test, OAP, and Acidize	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @6160' if determined excessive am't of water is entering hole from 6182-97'.
2. Perforate 5961-6132'.
3. Acidize 6182-97' w/1000 gals 15% NE if CIBP is not set @6160'.
4. Acidize 5961-6132' w/4800 gals 15% NE.
5. Test and report.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR - REG./PERM. DATE OCT 23 1980

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: