Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103	
Office District I	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.	
5 N. French Dr., Hobbs, NM 88240			30-025-20334	
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Aztec, NM 87410 Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-1565	
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	ES AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLU LTION FOR PERMIT" (FORM C-101) FO	G BACK TO A R SUCH	7. Lease Name or	Unit Agreement Name:
PROPOSALS.) 1. Type of Well:			State BA	
Oil Well Gas Well Other			8. Well No.	
2. Name of Operator Texaco Exploration & Production, Inc.			7	
3. Address of Operator			9. Pool name or Wildcat	
P. O. Box 3109, Midland, TX 79702			Vacuum Grayburg SA	
4. Well Location				
Unit Letter C: 660 feet from the North line and 1880 feet from the West line				
Section 36	Township 17-S Ra	nge 34-E	NMPM Lea	County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
11. Check A	ppropriate Box to Indicate Na	ature of Notice,	Report or Other I	Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WOR	к [_]	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE: DR				PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST CEMENT JOB			ND	
OTHER:		OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
1. RU on East-side. (Blinebry) RIH w/ws Tag TOC on CIBP @ 5850'. Fill 2 7/8" csg w/105 Sx plug 5850'-1570'				
2. RU on West-side. (San-Andres) RIH w/ws Tag TOC on CIBP @ 5220				
Fill 2 7/8" csg w/90 Sx plug 5220'-1570'				
 Cut both 2 7/8" csg strings @ 1570', L/D csgs. RIH w/ws to 1570', spot 125 Sx plug 1570'-1200' (T-Salt, 9 5/8" shoe) 				
WOC Tag 5. Displace hole w/MLF, 9.5# brine w/25# gel P/BBL				
6. 10 Sx Surf, I	nstall dry hole man	rker.		
0. 10 Sh Sals, 2			HOURS TROCK	ON MUST BE NOTIFIED 24 TO THE BEGINNING OF RATIONS FOR THE C-103 D.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE DATE 7/5/0/				
<i>()</i>	T. CORBITT		Tala	(915) phone No. 688-4438
Type or print name IAMES	1. COKBILL		100	PHOTO 101 BOU 11 1
(This space for State use)		•		
APPPROVED BYConditions of approval, if any:	TITLE_	<u> </u>		DATE

7

M

