

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

Formerly Vacuum Glorieta West Unit #131

WELL API NO.	3002520334
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1565
7. Lease Name or Unit Agreement Name	STATE BA
8. Well No.	7
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter C : 660 Feet From The NORTH Line and 1880 Feet From The WEST Line
Section 36 Township 17-S Range 34-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4001' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ TEST LOWER SAN ANDRES ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

THE SUBJECT WELL WAS FORMERLY THE VACUUM GLORIETA WEST UNIT # 131 - THE NAME HAS BEEN CHANGED TO STATE BA #7
1-09-01: MIRU. NUBOP. UNLOAD WS. TIH W/CONE BUSTER MILL. PU 2 1/16" TBG TO 2147'.
1-11-01: TIH W/TBG TO 6007'. CIRC CLN. TIH W/RBP & PKR. SET RBP @ 5888'. RAISE PKR TO 5878'.
1-12-01: SET PKR @ 5878'. TEST RBP @ 5888' TO 1500-OK. TEST WEST STRING FR RBP @ 5888' TO SURF TO 1500 PSI-OK. NUBOP. CUT
PARAFFIN TO 1500'. TIH W/OVER SHOT. GRAPPLE ON WS TO 3296'.
1-13-01: TIH W/FSH TOOL. TAG FSH @ 3918'. LD PMP & RDS.
1-15-01: TIH W/CB MILL & TBG TO 6007'. TIH W/RBP & PKR TO 3296'.
1-16-01: SET RBP @ 5888'. SET PKR @ 5855'. TEST RBP TO 1500 PSI-OK. TEST CSG. HAD LEAK. RAISE & RESET PKR @ 5273'. TEST 5273-
5855'.
1-17-01: NUBOP. NU HYD BOP. PKR @ 2966'. TEST 2966-SURF @ 1500 PSI-OK. LEAK FR 4845-4878'. TEST 4878-5888-OK.
1-18-01: REL RBP @ 5888'. TIH W/CIBP & SET @ 5850'. TIH W/DMP BAILER. DUMP 16' CMT ON CIBP.
1-19-01: DUMP CMT. TOP CMT @ 5815'. NUBOP. MOVE TO WEST STRING. TIH W/CIBP & SET @ 5850. RUN GR/CCL FR 5000-5600'.
1-22-01: OPEN WEST SIDE. TIH W/DMP BAILER. SPOT 35' CMT. PBTD @ 5815'. TIH W/MILL TO 5780'. DISPL W/2% KCL.
1-23-01: TIH W/TBG OPEN ENDED TO 5273'. SET ON SLIPS. CLOSE BOP.
1-30-01: RU LUB & TEST. TIH W/PERF GUN & PERF LOWER SAN ANDRES 5538-5538. PSI EAST SIDE - NO CHANGE IN PSI.
1-31-01: TIH W/PERF GUN. PERF LOWER SAN ANDRES @ 5324-5346, 5354-5400, 5450-5538.
2-01-01: WEST STRING: TIH W/PKR & SET @ 5287'. ACIDIZE LOWER SAN ANDRES 5324-5538 W/7500 GALS 15% NEFE.
2-02-01: WEST STRING: RU SWAB. FL @ SURF. REL PKR. END FL @ 2500'. SWABBING THRU 2-09-01:
2-09-01: RD SWAB. NUBOP. TIH W/CIBP & SET @ 5220'. TIH W/DMP BAILER. CAP CIBP @ 5220' W/35' CMT. TIH W/TBG. NUBOP. NU VALVE.
2-12-01: RIG DOWN. TEST WEST STRING TO 560 PSI FOR 30 MINS-OK. WELL IS SHUT IN - TEMPORARILY ABANDONED.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant

DATE 3/23/01

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY: TITLE

DATE

DeSoto/Nichols 12-93 ver 1.0

2A Vacuum Glorieta

