

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>B-2354</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
<b>Shell Oil Company (Western Division)</b>	<b>State A</b>
3. Address of Operator	9. Well No.
<b>Box 1509, Midland, Texas</b>	<b>5</b>
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <b>A</b> , <b>990</b> FEET FROM THE <b>north</b> LINE AND <b>660</b> FEET FROM	<b>Vacuum-Glorieta</b>
THE <b>east</b> LINE, SECTION <b>31</b> TOWNSHIP <b>17</b> RANGE <b>35</b> N14PM.	
11. Elevation (Show whether DF, RT, GR, etc.)	12. County
<b>3981' DF</b>	<b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods, pump & tubing & check for sand fill.
2. Frac down 5-1/2" casing with 25,000 gallons 10#/gallon brine water containing 1/2 - 1-1/2# 20-40 mesh sand per gallon and 20# BJ G-5, and 20# Adomite aqua per 1000 gallons. Precede frac with 2000 gallons (BJ) "J" type acid containing 3# G-11/1000 gallons.
3. Check for sand fill. Run production equipment and place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed By N. W. Harrison TITLE District Exploitation Engr. DATE Feb. 1, 1966

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: