

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator
TEXACO Inc.

3. Address of Operator
P.O. Box 728 Hobbs, NM 88240

4. Location of Well
UNIT LETTER **J** **1800** FEET FROM THE **South** LINE AND **1800** FEET FROM THE **East** LINE, SECTION **36** TOWNSHIP **17-S** RANGE **34-E** N.M.P.M.

5. Elevation (Show whether DF, RT, GR, etc.)
3991' (GR)

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-155

7. Unit Agreement Name
-

8. Farm or Lease Name
NM "O" St. NCT-1

9. Well No.
12

10. Field and Pool, or Wildcat
Blinebry Vacuum Glorieta &

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged Up.
2. Set CIBP in 2 7/8" Glorieta @ 5560' and dump 35 sx cement on top of plug.
3. Set CIBP in 2 7/8" Blinebry @ 5001' and dump 35 sx cement on top of plug
4. Spot 470' 13 sx cement plug in Glorieta from 3690'-3220'.
5. Spot 530' (13 sx) cement plug in Blinebry from 4740'-4210'.
6. Perforate Glorieta @ 1580' and pump 250 sx Class Cement down 2 7/8" Glorieta.
7. Temperature survey reveale cement from 1860'-1570'.
8. Pump 100 sx down 8 5/8" Csg.
9. Spot 720' (20 sx) cement plug in Blinebry from 1610'-890'.
10. Spot 5 sx cement plug at surface.
11. Install dry hole marker and clean up. Well P&A 5-3-77.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 5-5-77

APPROVED BY [Signature] TITLE Oil & Gas DATE 5-5-77

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 1977

OIL CONSERVATION COMM.
HOBBS, N. M.