State of New Mexico Fragy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobba, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088						" Late All Ind	30-025-	20446		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088						5. Indicate Type of Lease				
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410								STAT	EΧ	FEE
	District Rus, March, 1414	0/410					6. State Oil & E-8581-		G-47663	∤
	SUNDR	Y NOTICE	S AND REPO	ORTS ON WE	LLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							7. Lease Name or Unit Agreement Name			
1. Type	of Well:	(1 OT 114 O-10	I) FOR SUCH PA	OPUSALS.)						
OIL WELL		NET X	(OTHER			, State A	I Com		
1	of Operator						8. Well No.	TE COM		
Rea	d & Stevens,	Inc.					1			
3. Address of Operator P. O. Box 1518 Roswell. NM 88202							9. Pool name or Wildcat			
P. O. Box 1518 Roswell, NM 88202 4. Well Location							Lovington Queen			
	Unit LetterI	:660	Feet From The _	East	Line and _	1980	O Feet Fro	om TheS	outh	Line
	Section 14		Township 1	7S R	ange 36E	,	NMPM	Lea		G
			10. Elevati	on (Show whether	DF, RKB, RT, GR, a	etc.)	AIATT IAT	VIIII	7//////	County
WIIIII				821.8 GR	3833.5		******	_\////		
11.) Notice (heck App	propriate Box	to Indicate	Nature of Noti	ice, Re	port, or Othe	er Data		
						SUBS	BSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON					REMEDIAL WORK ALTERING CASING					
TEMPORA	IRILY ABANDON		CHANGE PLAN	us 🗍	COMMENCE DE	RILLING	OPNS.	PLUG AND	ARANDON	IMENT X
PULL OR A	ALTER CASING			4.5	CASING TEST		-	, 10 - , 11 -	7.04.11.001	men (A)
OTHER:_		· · · · · · · · · · · · · · · · · · ·			OTHER:					🗆
12. Descril	be Proposed or Complet SEE RULE 1103.	ed Operations	(Clearly state all p	ertinent details, a	nd give pertinent date	es, includi	ng estimated date	of starting any	proposed	
(1)	Spot 10 sack	s cement	@ 3,280 ' ,	W.O.C.,	no tag, pu	mp 80	sacks com	ent from	n aurfa	
(2)	Frace co	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	w.v.v., La	ig cement	top @ 2,265	1.	oucho cen	icire IIon	Sulla	ce
(2) (3)	Cut & pull 2	7/8" tu	ibing from	1,292'.						
	Load hole w/	mud.	0 1 0001							
(5)	Spot 25 sacks	s cement	@ 1,292',	W.O.C.,	tag cement 1	top of	f 1,187'.			
(3)	Spot 25 Sack	s cement	@ 300°.							
(0)	Spot 10 sacks	s cement	@ surface	, set P&A	marker.					
I hereby cer	tify that the information ab-	ove is true and o	omplete to the heat of	my knowledge == 4	haliaf		·····			
•				, six-asige and	vara.					

SIONATURE Petroleum Engineer Maxey, Jr. TYPE OR PRINT NAME TELEPHONE NO. 505/622-3770 (This space for State Use) OIL & GAS INSPECTOR JUL 07 1994

