

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-20505
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-155-1
7. Lease Name or Unit Agreement Name	New Mexico "O" State NCT-1
8. Well No.	15
9. Pool name or Wildcat	Vacuum Glorietta

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Texaco E&P, Inc.
3. Address of Operator P. O. Box 730 - Hobbs, NM 88240	4. Well Location Unit Letter <u>I</u> : <u>1800</u> Feet From The <u>South</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>17'S</u> Range <u>34'E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3997' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-27-95 Notify State of intent to move in and abandon well.
6-28-95 Circ. hole w/ 25# per bbl. salt gel mud.
"Y" 6-28-95 (Glorietta)-Set 2-7/8" cmt ret. @ 5750', sqz 90 sx cmt below, shut in @ 700 psi. Cap cmt ret w/ 10 sx cmt, cap TOC 5394'.
"Y" 6-28-95 35 sx cmt @ 4550, cal TOC @ 3129. "Y" 6-29-95-10 sx @ 2900', Cal TOC @ 2494'.
"X" 7-5-95 Milling @ 1486'. Made no hole.
"Y" 7-8-95 Drill out cmt to 5164'.
"Y" 7-12-95 10 sx cmt @ 5145', Cal TOC @ 4736'.
"Y" 7-13-95 Perf. @ 4200', set 2-7/8" Cmt ret. @ 2700', Circ. 150 sx cmt down "Y" to surf. on "X" string, displ. TOC 1/2 Bbl. below cmt. ret. in "Y". TOC 6' in "X" side.
"Y" 7-14-95 Cut 2-1/16" tbg @ 2375'.
"Y" 7-14-95 10 sx cmt @ 2375', TOC 1946'.
"Y" 7-14-95 10 sx cmt @ 1650', TOC 1221'.
"Y" 7-14-95 10 sx cmt @ 400' to C'.
7-14-95 Nipple down BOP, cap well and install dry hole marker. Clean location and move off.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Calder TITLE P&A Supervisor DATE 7/16/95
TELEPHONE NO. 915/335-5080

(This space for state use)

APPROVED BY Charlie Terrell TITLE OIL & GAS INSPECTOR DATE

CONDITIONS OF APPROVAL, IF ANY: