

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20527
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1497
7. Lease Name or Unit Agreement Name Vacuum Abo Btry 4 Tr. 6-E
8. Well No. 79 Tract 6
9. Pool name or Wildcat Vac Abo Reef

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook	
4. Well Location Unit Letter <u>EH</u> : <u>2311</u> Feet From The <u>North</u> Line and <u>992</u> Feet From The <u>West</u> Line Section <u>26</u> Township <u>17-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3916' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-21-90: MI and RU DDU. Install BOP. 7-23-90: Set pkr. at 8640'. Swab well.
7-24-90: Pump 2800 gals 15% NEFe II acid. Pump 540 gals gelled brine w/540#
rock salt. Swab. 7-25-90: Plug set @ 8640'. 7-26-90: Perf from 8527-8532'
8534'-8540'; 8576'-8578'; 8579'-8581' with 2 shots/ft on spiral phasing. Perf
8584'-8586'; 8609'-8614'; and 8615'-8620' with 2 shots/ft. Test packer & set @ 8443'.
Swab. 7-27-90: Acidize perforations 8527' to 8624'. Test to 4000 psi.
Pump 3200 gals 15% NEFe II HCl w/corrosion inhibitor and Tretolite AY-31 surfac-
tant. Pump 580 lbs. rock salt in 580 gals 40 lb. gelled brine. Flush w/38 bbls
fresh water. Avg. rate 3.2 BPM. 7-28-90 to 7-30-90: Swab total 12 hrs.
7-31-90: Temp. drop from report.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Reg. Proration Supv. DATE 08-07-90
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. 915-367-1488

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: