

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Big "6" Drilling Company		8. Farm or Lease Name Ora Jackson, et al
3. Address of Operator c/o Oil Reports & Gas Services, Box 763, Hobbs, New Mexico		9. Well No. 2
4. Location of Well UNIT LETTER G , 860 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 19 S RANGE 35 E N.M.P.M.		10. Field and Pool, or Wildcat Scharb Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3893 KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & abandoned 12/23/64 as follows:

25 sacks at 10,250 total depth, 25 sacks at 10,000, 25 sacks at 9300,
25 sacks 7890, 25 sacks at 6200, 25 sacks at 5400, 25 sacks at 4000
(8 5/8" casing shoe at 4002), shot & pulled 8 5/8" casing from 2500,
25 sacks at 2500, 25 sacks at 1800, 25 sacks at 400 (13 3/8" casing
shoe at 400) and 10 sacks in top with regulation marker. Rotary mud
between all plugs.

The Commission will be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. L. Smith* TITLE Agent DATE February 1, 1965

APPROVED BY *Leslie A. Clements* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: