Form 3160-5 (November 1983 (Formerly 9-33)	′	Stars New Mexico	Budget Bureau Expires Augus 5. LEASE DESIGNATION MM007465B W 6. IF INDIAN, ALLOTTE	No. 1004-0135 t 31, 1985 t and serial no. M1 - 052
OIL GAS WELL OTHER WIW			7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR			8. FARM OR LEASE NAME	
Hondo Oil & Gas Company 3. ADDRESS OF OPERATOR			Mescalero Ridge Unit 35	
4. LOCATION OF M See also space At surface		9. WHIL NO. 6 10. FIELD AND POOL, OR WILDCAT Pearl Queen		
660' FNL & 1980' FWL			11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA	
14. PERMIT NO.	4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)		Sec.35-T19S-R	34E
			Lea	NM
16.	Check Appropriate Box To Indicate I	Nature of Notice, Report, or C)ther Data	
NOTICE OF INTENTION TO:			ENT REPORT OF:	
FRACTURE TRE SHOOT OR ACT REPAIR WELL (Other) 17. DESCRIBE PROPE	DIZE ABANDON* CHANGE PLANS	completion of Recomple	ALTERING CA ABANDONMEN of multiple completion etion Report and Log for	on Well
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) 7/07/88 Rigged up pulling unit. Tried to release packer @ 4687' (Lok-Set top packer, 4490 tension, no slips). Rigged up Ryco. Ran free point. Free to 4670'. Tried to back off top packer twice @ 4687'. No break. Back off @ 4659' SLM. Left 1 jt. 2 3/8" J-55 plastic coated tubing, 1 Baker Lok-Set, 1 regulator with BP on bottom. 7/08/88 TOOH and TIH w/tension Guiberson. Worked packer in from 4514' to 4653'. Set packer. Most flow coming at bottom perfs. and thru the fish and packer. TOH. Laid down tension packer. TIH. Picked up Baker Lok-Set with Baker on-off tool (all nickel plated), profile stainless steel, 1.50" profile. Ran 143 jts. 2 3/8" plastic coated tubing, total of 4449'. Set @ 4465'. Tested tubing @ 5000#. 7/09/88 Unlatched on-off tool. Displaced annulus with 10# 2% KCL packer fluid containing corrosion inhibitor. Pressure tested annulus to 300 psi, ok. TIH w/wireline and retrieved blanking plug from profile nipple. Returned well to injection.				

*See Instructions on Reverse Side, NEW MEXICO CARLSBAU, NEW MEXICO