

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No. <b>E-7259</b>
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Brine Source Well</b>		7. Unit Agreement Name
2. Name of Operator <b>Hardin-Houston, Inc.</b>		8. Farm or Lease Name <b>Buckeye Brine Station</b>
3. Address of Operator <b>c/o Oil Reports &amp; Gas Services, Inc., Box 763, Hobbs, NM 88240</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>M</b> <b>330</b> FEET FROM THE <b>South</b> LINE AND <b>330</b> FEET FROM THE <b>West</b> LINE, SECTION <b>19</b> TOWNSHIP <b>17S</b> RANGE <b>35E</b> NMPM.		10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) <b>3989</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Well plugged and abandoned as follows:**

Set cement retainer in 8 5/8" casing at 1680.  
 Spot 100 sacks cement on top of retainer.  
 Tag top of plug @ 1362.  
 Loaded hole with mud.  
 Set 10 sacks cement at surface with regulation marker.  
 Cleaned & levelled location, ready for inspection.  
 Job complete 3/28/80

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Monica Hale</i></u>	TITLE <u>Agent</u>	DATE <u>2/25/81</u>
APPROVED BY <u><i>Eddie Dean</i></u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>MAR 3 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		