

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-936	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name -
2. Name of Operator Humble Oil & Refining Company		8. Farm or Lease Name New Mexico State J
3. Address of Operator Box 2100, Hobbs, New Mexico 88240		9. Well No. #3
4. Location of Well UNIT LETTER <u>M</u> , <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>19</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> NMPM.		10. Field and Pool, or Wildcat Vacuum Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3998 DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugs set as follows:

Plug #1 from 4952' to 4350' with 50 sxs cement.
Plug #2 from 3100 to 2870' with 50 sxs cement.
Plug #3 from 1786' to 1628' with 50 sxs cement.
Plug #4 from 25' to surface with 10 sxs cement.

Cut 4-1/2" casing at 3000' and pulled 93 joints.

Mud laden fluid between plugs.

Installed dry hole marker per NMOCC requirement.

Location cleaned and levelled. Ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Dist. Adm. Supvr. DATE 6-29-65

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: