	- 10-	Form C-103
DISTRIBUTION		Supersedes Old C•102 and C•103
SA ITA TE	NEW MEXICO OIL CONSERVATION COMMISSI	
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		A-1320
SUNDRY NO (CO NOT USE THIS FORM FOR PROPOSALS USE "APPLICATION FOR	TICES AND REPORTS ON WELLS s to drill or to deepen or plug back to a different rese r permit -" (form C-101) for such proposals.)	
		7. Unit Agreement Name
WELL OT	THER-	
2, Name of Operator		8. Farm or Lease Name
Exxon Corporation		New Mexico "K" State
3. Address of Operator		9. Well No.
Box 1600, Midland, TX 79	701	27
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER N 330	FEET FROM THE South 198	BO FEET FROM Vacuum Glorieta
West	28 17-5 35-1	
THE LINE, SECTION	TOWNSHIP RANGE	<u>з</u> NMPM. ())))))))))))))))))))))))))))))))))))
THELINE, SECTION	28 TOWNSHIP 17-S RANGE 35-1	<u>з</u> ммрм.
	TOWNSHIP RANGE RANGE	5 NMPM. 12. County
	15. Elevation (Show whether DF, RT, GR, etc.)	
	15. Elevation (Show whether DF, RT, GR, etc.) 3956 DF	12. County Lea
	15. Elevation (Show whether DF, RT, GR, etc.) 3956 DF opriate Box To Indicate Nature of Notice, R	12. County Lea
	15. Elevation (Show whether DF, RT, GR, etc.) 3956 DF opriate Box To Indicate Nature of Notice, R	12. County Lea eport or Other Data
	15. Elevation (Show whether DF, RT, GR, etc.) 3956 DF opriate Box To Indicate Nature of Notice, R	12. County Lea eport or Other Data
16. Check Appro NOTICE OF INTEN	15. Elevation (Show whether DF, RT, GR, etc.) 3956 DF opriate Box To Indicate Nature of Notice, R ITION TO: S	12. County Lea eport or Other Data UBSEQUENT REPORT OF: ALTERING CASING
16. Check Appro NOTICE OF INTEN	15. Elevation (Show whether DF, RT, GR, etc.) 3956 DF Opriate Box To Indicate Nature of Notice, R ITION TO: PLUG AND ABANDON REMEDIAL WORK	12. County Lea eport or Other Data UBSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
16. Check Appro NOTICE OF INTEN PERFORM REMEDIAL WORK	15. Elevation (Show whether DF, RT, GR, etc.) 3956 DF Opriate Box To Indicate Nature of Notice, R ITION TO: S Plug and abandon Remedial work Commence drilling op Change plans Casing test and cemen	12. County Lea eport or Other Data UBSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See Attachment

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED_ D. L. Clemmer	TITLE Unit Head	DATE 7-7-76
Orig. Signed by John Runyan		NUL 1 2 1976
	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JULG 1976

UIL CONSTRVATION COMM. HOBBS, N. M. Attachment to C-103

New Mexico "K" State

Proposed or Completed Operations

- 6-21-76 MIRU Baber Well Service, pulled rods and tbg., prep. to rn cmt retnr and sqz.
- 6-22-76 Rn Halliburton cmt retnr and tbg in hole set retnr @ 5995' pmpd into perfs 6052-6062' @ 6 BPM 1200 psi sqzd perfs w/150 sx Cl C cmt containing 5% salt and 0.3% Halad 22-A, MP 2500 psi reversed out 24 sx cmt., pulled tbg, to remove setting tool, rn 3-7/8" bit 4 3-1/8 drl collars and tbg in hole prep to drl retnr and cmt.
- 6-23-76 Ld hole w/8 bbls br wtr, tst csg to 1,000 psi, held O.K., drld cmt retnr @ 5995' and cmt to 6062' CO to 6190', tst perfs w/1,000 psi, held O.K.
- 6-24-76 Pulled tbg, drl collars and bit out of hole, perf 4½" csg from 6082-6086' (5 shots), 6096-6104' (9 shots), 6114-6120' (7 shots), total 21 shots, rn pkr and tbg in hole, set pkr @ 6072' and acidized perfs 6082-6120' w/3,500 gals 15% gelled HCl containing 2 gals. Corexit 7652 and 5#/gal 50-50 mixture BAF and rock salt to the last 2,500 gals. acid, MP 1400 psi, treated @ 5.6 BPM, ISIP on vacuum, unseat pkr, pull tbg and pkr out of hole.

6-25-76 Ran 2-3/8" tbg., Pump and rods in hole. RDU. FRW 6-30-76.

RECEIVED 1976 1976 RIL CONSERVATION COMM.

1

.