

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
A-1320

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG EACH TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator EXXON CORPORATION	8. Farm or Lease Name NEW MEXICO "K" STATE
3. Address of Operator P.O. BOX 1600, MIDLAND, TEXAS 79701	9. Well No. 28
4. Location of Well UNIT LETTER A , 330 FEET FROM THE EAST LINE AND 330 FEET FROM THE NORTH LINE, SECTION 32 TOWNSHIP 17-S RANGE 35-E N.M.P.M.	10. Field and Pool, or Wildcat VACUUM GLORIETA
15. Elevation (Show whether DF, RT, GR, etc.) 3966 DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER **PERFORATE + STIMULATE** ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PULL RODS AND LOWER TBG TO 6150, CLEAN OUT IF NECESSARY. USING A CSG. JET CUN PERFORATE FROM 6102 TO 6114 1 SPF. 13 SHOTS TOTAL. FROM MCCULLOUGH GRC LOG 5-24-64 CSG. COLLARS ARE AS FOLLOWS: 5926, 5958 1/2, 5991, 6023, 6055 1/2, 6088 3/4, 6120 1/2, 6153 1/2. RUN TREATING PACKER TO 6086. SPOT 2000 GALS. 15% NE HCl CONTAINING 2 GALS COREXIT 7652 TO PACKER. SET PACKER. ACIDIZE NEW PERFORATIONS 6102-6114 W/2000 GALS. ACID IN WORK STRING TO 1400 PSI SURFACE PUMP PRESSURE. OVERFLUSH W/40 BBLs. CLEAN BRINE CONTAINING 2 GALS. COREXIT 7652. PULL PACKER AND WORKSTRING, PLACE WELL ON PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **J. L. Clemmer** TITLE **UNIT HEAD** DATE **4-3-75**

Original by
John King
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: