Submit 3 Copies To Appropriate District Office <u>District I</u>	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District H	Dietriet II			WELL API NO. 30-025-20748	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease		
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE		
District IV 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.		
87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC'K TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name: Warn State A/C 1	
1. Type of Well:					
Oil Well Gas Well Other Morethen Oil Company					
2. Name of Operator Marathon Oil Company				8. Well No. #3	3
3. Address of Operator 2490				9. Pool name o	or Wildcat
P.O. Box 2409 , Hobbs, NM 88240				N. Vac. Abo/Vac. Upper Penn/Wolfcamp	
4. Well Location				1000	
Unit Letter F:	2,080 feet from the	Nor		1908 ,980 feet f	from the <u>West</u> line
Section 31	Township	17-S	Range 35-E	NMPM	County Lea
	10. Elevation (Show v		R, RKB, RT, GR, etc		distribution of the second
3,544' GL; 3,555' KB 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
11. Check A	Appropriate Box to In	dicate N			
NOTICE OF IN PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON		REMEDIAL WOR	SEQUENT R ^K □	EPORT OF: ALTERING CASING □
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ PLUG AND					PLUG AND
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN	ND 🗆	ABANDONMENT
OTHER:			OTHER:		
12. Describe proposed or completed starting any proposed work). SE recompilation.	l operations. (Clearly sta EE RULE 1103. For Mul	te all pert tiple Com	inent details, and given pletions: Attach we	ve pertinent dates ellbore diagram of	, including estimated date of f proposed completion or
See Attached plugging activity	y summary				
			2		
I hereby certify that the information a	boy is true and complete	e to the be	est of my knowledge	and belief	(4) (4) (4) (4) (4) (4) (4) (4) (4) (4)
W _/			is of my mis modely	Some bener.	· · ·
SIGNATURE		TITLE	Engineer	10/2	DATE 05/22/02
Type or print name James I (This space for State use)	Newman, P.E.	Triple N	SOMPLIANCE OF	Teleph	one No. 915-687-1994
	Ω Λ		" WUE OF	FICER	AA 44
APPPROVED BY Anny (Conditions of approval, if any:	Rollinson T	TTLE		·	DATE UL 02 2 1
GWW	<i>/</i> / 1				

Daily Activity Report

Marathon Oil Company Warn State A/C 1 #3 Lea County, New Mexico

Triple N Job #3774

04/27/02 MI Triple N rig #24 and plugging equipment.

04/29/02 Notified OCD, Paul Kautz. RU cementer on Wolfcamp and pumped 70 bbls, ½ BPM @ 1,400 psi. Final rate 2 BPM @ 800 psi, SI on vacuum. No communication to Abo or Penn strings. RU on Abo string, pumped 60 bbls 3 BPM @ 250 psi, on vacuum. No communication to Wolfcamp or Penn, or 9-5/8". Squeezed 330 sx C cmt down Wolfcamp string, displacing w/ 3 bbls, on vacuum.

04/30/02 RU cementer on Wolfcamp, and pumped 2 bbls, caught pressure, then 1 BPM @ 550 psi, pumped total of 9 bbls. Squeezed 35 sx C cmt down Wolfcamp string, locked up at 1,500 psi. PU 1 jt 1.90" tubing and washed out top of Wolfcamp string. RU on Abo string, loaded hole w/ 40 bbls and pressured up to 1,200 psi, no rate. RU on Penn string, loaded hole w/ 36 bbls and pressured up to 1,200 psi, no rate. RIH w/ wireline on Abo string, tagged PBTD @ 8,230'. RIH w/ wireline on Penn string, tagged PBTD @ 8,380'. Notified OCD, Paul Kautz. NU BOP on Abo casing and RIH w/ 1.90" tubing to 5,901'. RU cementer and pumped 10 sx C cmt 5,901 – 5,494'. POOH w/ tbg to 5,085' and pumped 10 sx C cmt, POOH w/ tbg and SI well, SDFN.

05/01/02 RIH w/ wireline on Abo string, tagged cmt @ 4,521'. RU on Penn casing. RIH w/ 1.90" tubing to 5,901'. RU cementer and pumped 10 sx C cmt 5,901 – 5,494'. POOH w/ tbg and WOC.

05/02/02 E.L. Gonzales w/ OCD on location. Tagged cmt on Penn string @ 4,622'. Sretched casings, Penn free @ 2,708', Abo free @ 3,054'. Cut Penn casing @ 2,864', casing free. Cut Abo casing @ 2,804', not free. POOH w/ Penn casing (Penn). Worked Abo casing, not free. Cut Abo casing @ 2,795', POOH. Circulated hole w/ mud and pumped 65 sx C cmt @ 2,795'.

05/03/02 E.L. Gonzales w/ OCD on location. Tagged cmt @ 2,594'. Finished circulating hole w/ mud and POOH to 1,550', pumped 65 sx C cmt 1,550 – 1,358' per EL Gonzales, no need to tag. Pumped 150 sx C cmt 410' to surface. RDMO.

05/14/02 Cut off wellhead and installed dry hole marker, cut off anchors, back-filled cellar and pit.

