

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Pennzoil United, Inc.		5. State Oil & Gas Lease No. OG 514
3. Address of Operator P. O. Drawer 1828 - Midland, Texas 79701		7. Unit Agreement Name
4. Location of Well UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 17-S RANGE 36-E N.M.P.M.		8. Farm or Lease Name State
15. Elevation (Show whether DF, RT, GR, etc.)		9. Well No. 1
		10. Field and Pool, or Wildcat Spencer Penn
		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned as follows:

Set C.I.B.P. on wire line at 9703'. Dumped 4 sx cement on top.
Shot 4 1/2" casing @ 8015'. Set 40 sk plug from 8000' - 7865'.
Set 40 sk plug from 6500 - 6365'
Set 40 sk plug from 5600 - 5465'
Set 40 sk plug from 4790 - 4655'
Shot 8 5/8" casing @ 2030' - Unable to pull
Shot 8 5/8" casing @ 1510' - Unable to pull
Shot 8 5/8" casing @ 1020' - Pulled and layed down same.
Set 50 sk plug from 1050 - 950'
Set 50 sk plug from 340 - 240'
Set 10 sk plug in surface.

Welded plate on top of 13 3/8" casing & erected dry hole marker.

Job complete @ 5:00 P.M. 3-23-72.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Drilling Superintendent DATE 3-29-72

APPROVED BY [Signature] TITLE Dist. L. Supv. DATE 007 26 1972

CONDITIONS OF APPROVAL, IF ANY: