

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20779
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Salt Water Disposal	7. Lease Name or Unit Agreement Name M. E. Hale
2. Name of Operator Phillips Petroleum Company	8. Well No. 11
3. Address of Operator Room 331, 4001 Penbrook St., Odessa, TX 79762	9. Pool name or Wildcat Vacuum-San Andres
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>2310</u> Feet From The <u>West</u> Line Section <u>35</u> Township <u>17-S</u> Range <u>34-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) NA	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Set CIBP & TA Well. <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/24/91: RU DDU. Unseat inj pkr & COOH w/tbg. GIH w/pkr & RBP. Set RBP @ 4975'. Test csg to 500#, held OK. Retrieve RBP & COOH w/tbg & tools. SD.

6/25/91: GIH w/CIBP. Set at 4875'. RU Halliburton to dump 3 sks cmt on top of CIBP. GIH w/dump bailer. Bailer stuck at 2932'. Dumped cmt. GIH w/bit & tbg and try to circ out cmt. Tag top of CIBP. COOH w/tbg & bit. SD.

6/26/91: GIH w/3-1/8" dump bailer. Bailer stuck again at 2942'. COOH w/bailer. Press up on csg & CIBP to 500#. Run chart for NMOC. RD & MO DDU. Well TA'd according to state regulations. Wellbore full of inhibited brine.

Request temporary abandonment status for a period of five (5) years. Pressure chart sent to NMOC Hobbs Office.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv., Regul. & Prora. DATE 7/3/91
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. (915)368-1488

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 7-1-96

6-25-91