STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we. er torics acceives	Ţ	
DISTRIBUTION		
SANTA FE	T	
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 .

	L	SANTA FE.	NEW MEXICO 87501	Revised 10-1-78
FILE		·		5a. Indicate Type of Leuse
U.S.G.S.				State X Foo
OPERATOR				5, State Oil & Gas Lease No.
OF EAX TOA		,		
	610105	V.1071656 1115 55505		B-2423
(00 NOT U	SUNDK	LY NUTICES AND REPORT POSALS TO DRILL OR TO DEEPEN OR	S ON WELLS PLUG BACK TO A DIFFERENT RESERVOIR.	
1.	USE "APPLICATI	ION FOR PERMIT -" (FORM C-101) F	OR SUCH PROPOSALS.)	
WELL XX	GA8			7, Unit Agreement Name
2. Name of Operato	WELL	OTHER.		
1				8. Farm or Lease Name
SHELL OIL				STATE "F"
1		TV 77001		9. Well No.
P. U. BUX	991, HOUSTON	I, IX //001		3
4. Ebediton of wer		100	T.1	10. Field and Pool, or Wildcat
UNIT LETTER _	M8	FEET FROM THE SUU	TH LINE AND 800 FE	VACUUM (GLORIETA)
UEC.	T	22	17.0	
THE WES	LINE, SECTIO	on Z9 township	17-S RANGE 35-E	_ HMPM. (
mmm	mmm	WWW. Elman (C)	Lata DC DT CD	
		15. Elevation (Show w	hether Dr., KI, GR, etc.)	12. County
İmmi		3979' DF		LEA (\\\\\\\\\
10.	Check A	Appropriate Box To Indic	ate Nature of Notice, Report	or Other Data
	NOTICE OF IN			QUENT REPORT OF:
PERFORM REMEDIA	L WORK	PLUG AND ABANDOS	REMEDIAL WORK	XX * ALTERING CASING
TEMPORARILY ABAN	10 ON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CAS	11NG	CHANGE PLANS	CASING TEST AND CEMENT JOB	
			OTHER	
OTHER				
17. Describe Propo work) SEE RU	baed or Completed Op: LE 1103.	erations (Clearly state all pertine	nt details, and give pertinent dates, is	ncluding estimated date of starting any proposed
	0	01 1		
8-22-81:	Set RBP @594	O' and spotted 2 sx	20-40 sand on top.	
8-24-81:	Perf'd 4 squ	eeze holes in 4 1/2"	csg @2700' to 2702'.	
8-24-81: 8-25-81:	Perf'd 4 squ Pumped 2000	<pre>eeze holes in 4 1/2" sx HOWCO Lite cmt + 8</pre>	csg @2700' to 2702'. B#/sx salt plus 300 sx	Class "C" cmt + 2% CaCl ₂ .
8-24-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20	csg @2700' to 2702'. B#/sx salt plus 300 sx O2'. Pumped 1250 sx HO'	Class "C" cmt + 2% CaCl ₂ . WCO LITE cmt + 8#/sx salt
8-24-81: 8-25-81: 8-26-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx	<pre>eeze holes in 4 1/2" sx HOWCO Lite cmt + 8</pre>	csg @2700' to 2702'. B#/sx salt plus 300 sx O2'. Pumped 1250 sx HO'	Class "C" cmt + 2% CaCl ₂ . WCO LITE cmt + 8#/sx salt
8-24-81: 8-25-81: 8-26-81: 8-27-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC.	eeze holes in 4 1/2" sx HOWCO Lite cmt + 8 ze holes @2000' - 200 Class "C" cmt w/2% C	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO' aCl ₂ .	WCO LITE cmt + 8#/sx salīt
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes	eeze holes in 4 1/2" sx HOWCO Lite cmt + 3 ze holes @2000' - 200 Class "C" cmt w/2% Cotted squeeze @2000' to	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho	WCO LITE cmt + 8#/sx salīt ld.
8-24-81: 8-25-81: 8-26-81: 8-27-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230	eeze holes in 4 1/2" sx HOWCO Lite cmt + 3 ze holes @2000' - 200 Class "C" cmt w/2% Cotted squeeze @2000' to	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho	WCO LITE cmt + 8#/sx salīt
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ .	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' o	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped	WCO LITE cmt + 8#/sx salt ld. lOO sx HOWCO Thick-set cmt +
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s.	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' of x HOWCO Thick-set cm	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO'aCl ₂ . D 1000 psi. Did not hof sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h	WCO LITE cmt + 8#/sx salt ld. loo sx HOWCO Thick-set cmt + rs.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-3-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Cd ted squeeze @2000' to 0' and spotted 15' of x HOWCO Thick-set cm ted squeeze holes to	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO' aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins.	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s. Pressure tes Pressure tes	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Cd ted squeeze @2000' to O' and spotted 15' of x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO' aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot	WCO LITE cmt + 8#/sx salt ld. loo sx HOWCO Thick-set cmt + rs.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-3-81: 9-5-81;	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Cd ted squeeze @2000' to O' and spotted 15' of x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO' aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins.	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-3-81: 9-5-81;	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed WOC.	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' or x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO' aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ .	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-3-81: 9-5-81; 9-6-81: 9-10-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed WOC. Pressure tes	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' or x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so ted squeeze holes to	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO' aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-3-81: 9-5-81;	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed WOC. Pressure tes	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' or x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO' aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ .	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-3-81: 9-5-81; 9-6-81: 9-10-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed WOC. Pressure tes Returned wel	eeze holes in 4 1/2" sx HOWCO Lite cmt + 3 ze holes @2000' - 200 Class "C" cmt w/2% Cated squeeze @2000' to 50' and spotted 15' of x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 stated squeeze holes to 1 to production.	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO'aCl ₂ . D 1000 psi. Did not hof sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ .	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-3-81: 9-5-81; 9-6-81: 9-10-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed WOC. Pressure tes Returned wel	eeze holes in 4 1/2" sx HOWCO Lite cmt + 3 ze holes @2000' - 200 Class "C" cmt w/2% Cated squeeze @2000' to 50' and spotted 15' of x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 stated squeeze holes to 1 to production.	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO' aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ .	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-5-81; 9-6-81: 9-10-81: 9-16-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed WOC. Pressure tes Returned wel	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' or x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so ted squeeze holes to 1 to production. EXICO OIL CONSERVATION	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ . 1000 psi for 15 mins -	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-5-81; 9-6-81: 9-10-81: 9-16-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed WOC. Pressure tes Returned wel	eeze holes in 4 1/2" sx HOWCO Lite cmt + 3 ze holes @2000' - 200 Class "C" cmt w/2% Cated squeeze @2000' to 50' and spotted 15' of x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 stated squeeze holes to 1 to production.	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ . 1000 psi for 15 mins -	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-5-81; 9-6-81: 9-10-81: 9-16-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s. Pressure tes Pressure tes Re-squeezed WOC. Pressure tes Returned wel * PER NEW M	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' or x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so ted squeeze holes to 1 to production. EXICO OIL CONSERVATION Above is true and complete to the	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ . 1000 psi for 15 mins - DN COMMISSION REQUEST.	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid. held OK.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-5-81; 9-6-81: 9-10-81: 9-16-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s. Pressure tes Pressure tes Re-squeezed WOC. Pressure tes Returned wel * PER NEW M	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' or x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so ted squeeze holes to 1 to production. EXICO OIL CONSERVATION Above is true and complete to the	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ . 1000 psi for 15 mins - DN COMMISSION REQUEST.	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid. held OK.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-5-81; 9-6-81: 9-10-81: 9-16-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s. Pressure tes Pressure tes Re-squeezed WOC. Pressure tes Returned wel * PER NEW M	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' or x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so ted squeeze holes to 1 to production. EXICO OIL CONSERVATION Above is true and complete to the	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ . 1000 psi for 15 mins - DN COMMISSION REQUEST.	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-5-81; 9-6-81: 9-10-81: 9-16-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx WOC. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s. Pressure tes Pressure tes Re-squeezed WOC. Pressure tes Returned wel * PER NEW M	eeze holes in 4 1/2" sx HOWCO Lite cmt + 2 ze holes @2000' - 20 Class "C" cmt w/2% Co ted squeeze @2000' to O' and spotted 15' or x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so ted squeeze holes to 1 to production. EXICO OIL CONSERVATION Above is true and complete to the	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ . 1000 psi for 15 mins - DN COMMISSION REQUEST.	WCO LITE cmt + 8#/sx salt ld. l00 sx HOWCO Thick-set cmt + rs held OK. ted 150 gals 15% NE acid. held OK.
8-24-81: 8-25-81: 8-26-81: 8-27-81: 8-29-81: 8-31-81: 9-1-81: 9-5-81; 9-6-81: 9-10-81: 9-16-81:	Perf'd 4 squ Pumped 2000 Shot 4 squee plus 300 sx W0C. PRessure tes Set RBP @230 3% CaCl ₂ . Pumped 300 s Pressure tes Pressure tes Re-squeezed W0C. Pressure tes Returned wel * PER NEW M	eeze holes in 4 1/2" sx HOWCO Lite cmt + 3 ze holes @2000' - 200 Class "C" cmt w/2% Co ted squeeze @2000' to 0' and spotted 15' of x HOWCO Thick-set cm ted squeeze holes to ted squeeze holes @2 perfs @2700' w/300 so ted squeeze holes to 1 to production. EXICO OIL CONSERVATION A. J. FORE	csg @2700' to 2702'. B#/sx salt plus 300 sx D2'. Pumped 1250 sx HO aCl ₂ . D 1000 psi. Did not ho f sand on top. Pumped t + 3% CaCl ₂ . WOC 24 h 1000 psi for 15 mins. 700' to 1000 psi. Spot x Class "C" + 3% CaCl ₂ . 1000 psi for 15 mins - DN COMMISSION REQUEST.	WCO LITE cmt + 8#/sx salt Id. 100 sx HOWCO Thick-set cmt + rs. - held OK. ted 150 gals 15% NE acid. held OK. TING OATE NOVEMBER 19, 1981