

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1576

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company	8. Farm or Lease Name State B 1576
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 6
4. Location of Well UNIT LETTER K 2310 FEET FROM THE West LINE AND 2310 FEET FROM THE South LINE, SECTION 32 TOWNSHIP 17S RANGE 35E NMPM.	10. Field and Pool, or Wildcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) 3964' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER Add Perfs, Stimulate - Same Zone ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Present Glorieta perfs 6074-6087', 6094-6101' = 40 holes.
RU, POH w/rods & pump. Install BOP & POH w/tbg. CO hole to 6150' w/bit & scraper. Perforate Glorieta w/add'l perfs 6120-30' w/1 JSPF. Set pkr @ 6110'. Acidize perfs 6120-30' w/1500 gals 15% NEFE acid. Flow or swab back & test. POH w/pkr. RIH w/RBP & pkr, set BP @ 6110'. Spot 100 gals 15% acid 6074-6101', set pkr @ 6000' & acidize perfs 6074-6101' w/4000 gals 15% acid & xylene (75% HCL & 25% xylene) in 3 stages. Flow & swab back to test. POH w/pkr & RBP. Perf upper Glorieta 5992-96', 6002-12', 6015-19', 6022-32', 6048-52' w/1 JSPF = 37 holes. RIH w/RBP & pkr. Set BP @ 6065'. Spot 100 gals 15% acid 5992-6052'. Set pkr @ 5900' & acidize w/4500 gals 15% acid. Flow & swab back to test. POH w/pkr & RBP. RIH w/compl assy, set SN @ 6130'. RIH w/pump & rods, return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie SeayTITLE Drig. Engr.DATE 7/19/83

ORIGINAL SIGNED BY EDDIE SEAY

APPROVED BY OIL & GAS INSPECTOR

TITLE _____

DATE

JUL 21 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUL 20 1983
O.C.D.
HOBBS OFFICE