

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. <b>30-025-20883</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>B-1839-1</b>
7. Lease Name or Unit Agreement Name: <b>VACUUM GLORIETA EAST UNIT TRACT 26</b>
8. Well No. <b>#01</b>
9. Pool name or Wildcat <b>VACUUM GLORIETA</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3935'</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
**Phillips Petroleum Company**

3. Address of Operator  
**4001 Penbrook Street Odessa, TX 79762**

4. Well Location  
Unit Letter **D** : **990** feet from the **NORTH** line and **330** feet from the **WEST** line  
Section **27** Township **17S** Range **35E** NMPM County **LEA**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐

OTHER: **REQUEST 5 YEAR T.A. STATUS OF SHUT-IN WELL** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

05/08/01 ND WH NU BOP GIH W/BIT/SCRAPR 4-1/2 & 2-3/8 TBG 128 JTS 3983' RU HOT OILER  
PMP 30 BBL HOT WTR WK THRU TIGHT SPOT RAN 195 JTS 6125' COOH W/TBG/BIT/SCRAPR  
GIH W/4-1/2 EZ DRL CIBP 2-3/8 SET TL 4.7' 194 JTS 2-3/8 TBG SET CIBP 6086'  
CIRC W/FW & 1% CORR INHIB 110 BBL TST CSG & CIBP T/500 PSI BOP LEAKNG.  
05/09/01 PULL BOP & FLNG TAPE WH FLNG PUT BOP/FLNG BK ON LD TST CSG & CIBP 540 PSI 30  
MIN OK POOH W/TBG & SET TL ND BOP NU WH RD DDU RUN TST CHART (ATTACHED)  
DROP F/REPORT.

**REQUEST 5 YEAR T.A. STATUS FOR WELL.**

This Approval of Temporary  
Abandonment Expires 6/4/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE **SUPERVISOR, REG/PRORATION** DATE **5-29-01**

Type or print name **L. M. SANDERS** Telephone No. **915/368-1488**

(This space for State use)

APPROVED BY [Signature] TITLE **OFFICIAL** DATE **JUN 02 2001**  
Conditions of approval, if any: