Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 Revised March 25, 1999
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
District II	OIL CONSERVATION DIVISION		30-025-20942
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	,		B-1722-1
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:			7. Lease Name or Unit Agreement Name: New Mexico N. State 6
Oil Well X Gas Well Cther		8. Well No.	
Name of Operator Chevron Texaco Corporation		VGWU#37 # 6	
3. Address of Operator		9. Pool name or Wildcat	
P.O. Box 3109 Midland, Texas 79702		Vacuum Glorieta West Unit	
4. Well Location 460			
Unit Letter L:	1980 feet from the South	line and4	ı
Section 30		Range 35E	NMPM Lea County
	10. Elevation (Show whether L	OR, RKB, RT, GR, etc	c.)
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	RK
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.[] PLUG AND X ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A CEMENT JOB	
OTHER:		OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.			
1. RIU on X-side set 2 7/8 CIBP @ 5975' (Glorieta) Fill 2 7/8 csg. w/150 sx. Plug 5975' to surf			
2. RIU on Y-side Tag CIBP @ 6325' (ABO) Fill 2 7/8 csg. w/160 sx. plug 6325' to surf			
3. RIU on Z-side Tag CIBP @6300' Fill 2 7/8 csg. w/80 sx. Plug 6300' to 3800' Tag @ 3818' (Worksamp)			
4. Perf 6 holes @ 3800' sqz. w/75 sx. 3800' to 2800' (Queen) Tag @ 2767'			
5. Perf 6 holes @ 2767' sqz. w/75 sx. 2767' to 1650' (B-Salt-Yates) Tag @ 1581'			
6. Perf 6 holes @ 1581' sqz. w/130 sx. 1581' to surf (13 3/8 shoe T-Salt) Tag @ surf			
7. Install dry hole marker	2/21/01		10 2 2 8 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE SIGNATURE	TITLE_	MANAGER	DATE <u>/2/21/0/</u>
Type or print name Juney BAGLEY Telephone No. 9/5 683-4996			
(This space for State use)			
APPPROVED BY Conditions of approval, if any: DATE DATE			
GWW	V		m.P.
			<i>' U</i>

50 S