Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N French Dr., Hobbs, NM 87240 District II 30-025-20962 OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III STATE x 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 B-1030-1 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Texaco-Mobil State 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 8. Well No. Prize Operating Company 3. Address of Operator 9. Pool name or Wildcat 3500 William D. Tate, Suite 200, Grapevine, Texas 76051 Vacuum, Abo N/Upper Penn/Wolfcamp 4. Well Location 2080 Unit Letter feet from the North line and 560 feet from the line Section 17S 25 Township Range NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3986' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK **ALTERING CASING TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT** PULL OR ALTER CASING CASING TEST AND **MULTIPLE CEMENT JOB** COMPLETION OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Prize Operating Company respectfully request approval to Plug & Abandon the above mention well. Please find attached well schematic and plugging procedure for your review and approval. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Regulatory Analyst SIGNATURE. __DATE __**10-12-2001** Type or print name Don Aldridge Telephone No. 817-424-0454 (This space for State use)

_ TITLE_


APPROVED BY

Conditions of approval, if any:

Texaco-Mobil State #1 Plug and Abandon

Procedure:

- 1. MIRU Workover Rig. Blow down all three 2 7/8" production strings.
- Penn String: Rig up pump truck and squeeze perforations. Fill Tubing to surface with cement.
- 3. Wolfcamp String: Rig up pump truck and squeeze perforations. Fill tubing to surface with cement.
- 4. Abo String : Rig up pump truck and squeeze perforations. Fill tubing to surface with cement.
- 5. Dig out and cut off well head 3' below ground level. Weld ½" steel Plate on top of casing.
- 6. RDMO. Clean location.



LEASE: TEXACO-Mobil "State" Well No. 1 FIELD: Vacuum (North Abo, Wolfcamp and Upper Pennsylvanian DATE: July 31, 1964 COMPLETED

BEC. 25; T175; R 34E; 2080 FSL + 560' FEL LEA COUNTY, NM