

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-2729	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Hondo Oil & Gas Company		8. Farm or Lease Name Hondo "B" State
3. Address of Operator P.O. Box 1610, Midland, Texas 79702		9. Well No. 1
4. Location of Well UNIT LETTER 0 560 FEET FROM THE South LINE AND 1880 FEET FROM East THE LINE, SECTION 6 TOWNSHIP 19S RANGE 35E NMPM.		10. Field and Pool, or Wildcat Scharb Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3919 DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to P&A as follows:

- 5 sx 9935-9970. CIBP w/35' cmt. (Bone springs perfs 10,115-10,154').
- 5 sx 9465-9500. CIBP w/35' cmt. (Bone springs perfs 9561-9575').
- 100 sx 7700-7800. Perfs @ 7800. CR @ 7700. (Top of Bone Springs)
- 100 sx 5050-5150. Perfs @ 5150. CR @ 5050. (Top of San Andres)
- 100 sx 3950-4060. Perfs @ 4060. CR @ 3950. (Intermediate shoe)
- Jet cut 5-1/2" @ 3700' & POH.
- 50 sx 3150-3330. (B-salt).
- 50 sx 1980-2160. (T-salt).
- 150 sx 0-470. (Surface)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

915-684-0312

SIGNED Ken W. Gosnell

TITLE Engr. Tech. Spec.

DATE 12-17-85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

DEC 23 1985

APPROVED BY 1

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
DEC 20 1985
O.C.T.
HQB22 OFFICE