NO. OF COPIES RECEIVED			Form C-103 Supersedes Old
DISTRIBUTION			C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSE	RVATION COMMISSION	Effective 1-1-65
FILE			The state of the s
U.S.G.S.	1		State X Fee
LAND OFFICE			5. State Oil & Gas Lease No.
OPERATOR	1		
			£-6005
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)			7. Unit Agreement Name
OIL X GAS WELL	OTHER-		8. Farm or Lease Name
2. Name of Operator			
Mallerd Fetroleum, Inc.			State 9. Well No.
a library of Changton			g. Well No.
1206 V . J Tower. Midland, Texas 79701 4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER			Pearl dueen
UNIT LETTER AND FEET FROM THE GOLDEN LINE AND FEET FROM			
THE WOSE LINE, SECTI	ION <u>46 TOWNSHIP 10.8</u>	RANGE NMPN	
15. Elevation (Show whether DF, RT, GR, etc.)			12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
NOTICE OF I	NTENTION 10:	33232432	., .,
[]	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CEMENT JOB	
PULL OR ALTER CASING		OTHER	
OTHER			
	Operations (Clearly state all pertinent dete	ails and give pertinent dates, including	ng estimated date of starting any propose
17. Describe Proposed or Completed (work) SEE RULE 1703.	Sperations (Crearly state art pertinem dete	tio, and give promise	
1. Rig up (1.).	o came Pallers		
u. Pull rous out pump 3. Spot (40 sex) plan over percorations 46 d- 2009			
3. Spot (40 sex) plan area permorantons 40 (5-77) 4. Pull 2-3/8 (Maria)			
5. Attempt to paid. 141/ 0 ldf & 15.5% Casing Erom top to compact the lift.			
6. Spot 190 ar. (10 sex) plag at 5-1/2" cosing sect.			
7. Spot 100 11. (1 sex) plug Mou-1361 (Top 42 3011)			
8. Spot 100 it. (4. sex) plug 150-250 (Base of sar ace cash			
o and the second of surface and install surface marker			

18 I hereby certify that the information above is true and complete to the best of my knowledge and belief.

9. Spot 1) sax ; n at surface and install surface marker