

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No. B-4119 ASSIGN 6	
7. Unit Agreement Name -	
8. Farm or Lease Name STATE "K"	
9. Well No. 1	
10. Field and Pool, or Wildcat WILDCAT	
12. County LEA	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER-
Name of Operator ESTATE OF FRED TURNER, JR.		
Address of Operator Box 910, MIDLAND, TEXAS 79702		
Location of Well UNIT LETTER K , 2165 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 4 TOWNSHIP 17-S RANGE 36-E N.M.P.M.		

15. Elevation (Show whether DF, RT, GR, etc.)
3888.6 G.L.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


SEE ATTACHED SHEET FOR COMPLETE PLUG & ABANDONMENT OPERATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Chas. A. Lutz</u>	TITLE <u>PROD. SUPT.</u>	DATE <u>1/26/79</u>
APPROVED BY <u>Eddie Dean</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>MAR 27 1979</u>
CONDITIONS OF APPROVAL, IF ANY:		

ESTATE OF FRED TURNER, JR.

State K No. 1 Lse No. B-4119 Assign 6
Unit K 2165' FSL, 1980' FWL Sec 4
T 17 S, 36 E, Lea Co. Wildcat.
3888.6 G.L. elevation



P & A OPERATION.

PBCP Services Inc. RU on Location 12-22-78
Pulled & Lay down 84 1/2\" Rods, 153 3/4\" Rods w/ Pump.
12-27-78. CUT stuck Tbg @ 6100'. Spot 305x CMT 6100' - 5955'
Mix SAIT Gel & BAINE & Lead hole. 9.5\" plus. Mud.
12-29-78 Free 5 1/2\" @ 3497 Pull 108 Jts 3525.29' overall ft.
1-3-79 Run Tbg 3534' hole full Mud. Spot 355x 3534 - 3380'
Spot 450x 2073 - 1923 calculated Top in 8 5/8\"
1-5-79 Shot & Free 8 5/8\" 1181 Pull 36 Jts 1177.57'
1-6-79 Run Tbg to 1240'. Spot 605x Top Plug 511 1125'.
1-8-79 Run Tbg To 414 Spot 805x Top Plug 293
Spot 105x plug in surface 0 - 14' w/
5 1/2\" csg Marker in Top.
Job. Complete. Rig down & Move off.
Haul material off Location.
Location cleaned, Pits filled & level.
All work completed about 1-12-79

1125' - 1338' surface left in hole.
3380' - 3534' left in hole.
3540' - 5955' left in hole.

Completed by [signature]

CHAS. A. LUTZ