Form 3160-5 (November 1983) (Formerly 9-331)	UNI _D STA DEPARTMENT OF TH BUREAU OF LAND MA	E INTERIOR	SUBMIT THE TRIPL. (Other instructions on verse side)		No. 1004⊕135 t 31, 1985	
	NDRY NOTICES AND Restorm for proposals to drill or to de Use "APPLICATION FOR PERMIT			6. IF INGIAR, ALLOTTE	E OR TRIBE NAME	
OIL GAS WELL	OTHER SWD			7. UNIT AGREEMENT N	AME	
2. NAME OF OPERATOR Hondo Oil & Gas Company			ł	8. FARM OR LEASE NAME Mescalero Ridge Unit 35		
3. ADDRESS OF OPERAT	O B.			9. WELL NO.	Hade out 6 33	
P.O. Box 2208, Roswell, NM 88202 1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface FWL					10. FINID AND POOL, OR WILDCAT Pearl Oueen	
1980' FSL & 990' FSL				11. SEC., T., B., M., OR	11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA	
14. PERMET NO.	15 FLEVATIONS (S	how whether DF, RT, GR,	etc.)	Sec. 35, T1	95, R34E 1 13. STATE	
16.	3713' (Lea	<u>NM</u>	
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
TEST WATER SHUT FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) Run 17. DESCRIBE PROPOSED proposed work, nent to this work.	MULTIPLE COMPLETE ABANDON* CHANGE PLANS Integrity Test: OR COMPLETED OPERATIONS (Clearly state) If well is directionally drilled, give is		Completion or Reco	ALTERING C ABANDONME lits of multiple completion inpletion Report and Log for tes, including estimated da tical depths for all marker	on Well	
	AD-1 Tension Pkr 2 3/8 IPC tbg Perfs @ 4604'-503					
Propose	to run csg Integri	ty test per	BLM request	as follows:		
(1)	RU pump truck w/	pressure r	ecorder on c	sg.		
(2)	Pressure csq to	500 psi & m	onitor for l	5 minutes.		
					E Zi	
	the second of the sealing.				CEI	
Straje					EIVE	
Like Ap				the second	=: O	
by S				₩ (일	<u>ය</u>	
-	t the foregoing is true and correct 1. Bettrest Jr	TITLE Petrol	eum Engineer	DATE 4/1	0/89	
(This space for Fed	leral or State office use)					
APPROVED BY	nammond hanv	FOR: CHIEF ET	শাসন ্ধ হ শস্ত্ৰ প্ৰত	DATE 40	20-89	
J.	Stubbs Handley	e Instructions on R	C+ 1			
Fil	H 7300	e instructions on K	everse bide			