

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-155

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Texaco Inc.	8. Farm or Lease Name N.M. "O" State Net-1
3. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240	9. Well No. 25
4. Location of Well UNIT LETTER J 2090 FEET FROM THE South LINE AND 2086 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 17-S RANGE 34-E N.M.P.M.	10. Field and Pool, or Wildcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) 3990' (GR)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRR. Pull rods and pump. Install BOP. Pull tubing.
2. TIH with bit. Clean out cased hole to 6185'. POH.
3. Perforate Glorieta 2 JSPI at 6131', 33, 39, 43, 48, 50, 52, 57, 6160' (18 shots total). POH.
4. Set packer at 6105'. Break down perforations 6131-6160' with 2,000 gals 20% NEFE HCl and 24 ball sealers. Swab.
5. Reset packer at 5700'. Acidize Glorieta perforations at 5930'-6160' with 10,000 gals gelled 20% NEFE HCl in five stages, with 400 lbs rock salt between stages.
6. Swab back residue. POH with packer.
7. Run pumping equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. Gernandt 393-4031 TITLE Area Superintendent DATE APR 22 1987

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY DATE TITLE DATE
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
APR 21 1987
OCD
HOBBS OFFICE