

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-155-1	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)


1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator TEXACO Inc.		8. Farm or Lease Name NCT-1 New Mexico '0' State
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240		9. Well No. 25
4. Location of Well UNIT LETTER J , 2090 FEET FROM THE South LINE AND 2086 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 17 RANGE 34 N.M.P.M.		10. Field and Pool, or Wildcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) 4001' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER Perf. & Acidize <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull pumping equipment.
2. Perforate w/ 2 JSPF from 6008-10, 6019-21, 25, 38-40, 50-52, 59-61, 68-71, 85-87, 95, & 6100'.
3. Acidize w/ 4000 gals. 20% NEA.
4. Swab, test, & return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  TITLE Asst. Dist. Supt. DATE 9-8-72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supt. DATE SEP 11 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 6 1972

U.S. DEPARTMENT OF AGRICULTURE
WASHINGTON, D.C. 20250