

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002521675
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-1520
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	23
9. Pool Name or Wildcat	VACUUM GLORIETA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4004'	

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter F 2310 Feet From The NORTH Line and 1860 Feet From The WEST Line
Section 25 Township 17S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4004'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-06-97: TAG CIBP @ 5803'. TEST BOP TO 1200#. RUN GYRO.
11-07/11-12-97: DRILL
11-13-97: TIH W/JNK BASKET. TIH W/WL SET & TBG RBP SET @ 5008'.
11-14-97: ND HYD BOP. NU BOP. UNLOAD, RACK, TALLY 2 7/8" WS. TIH W/RETR TOOL. PU 2 7/8" TBG. REL RBP.
11-15-97: TIH W/PKR, SN, WS. PSA 5673'. TEST CSG TO 500#-OK. SWAB.
11-19-97: LD SWAB. REL PKR & TOH W/TBG & PKR.
11-20-97: TIH W/MTRS, SEAL, SEPERATOR, PUMP, 2 7/8" TBG. NDBOP. NUWH. INSTL FLOW LINE. WELL PUMP UP @ 3:30 PM.
2-14-98: NDWH, NUBOP. TOH W/2 7/8" TBG & SUB PUMP & MTRS.
2-16-98: TIH W/BIT & CSG SCRAPER ON TBG TO 5764'. TIH W/STRADDLE PKRS.
2-17-98: TIH W/PKR TO 7450' & SET. RU & SWAB.
2-19-98: WRK STUCK PKRS LOOSE & MOVE TO 7049-7256'. PSI TBG TO 800# & SET PKR. RU & SWAB.
2-20-98: REL PKR. PULL 6 JTS TBG. RESET PKR @ 6856-7063'. RU & SWAB.
3-10-98: SWAB. BROKE SWAB LINE. BTM PKR @ 5707'. TOP PKR @ 5349'. REL BOTH PKRS. RECVD FSH. RAN 7" RBP & PKR TO 4700'.
3-11-98: SET RBP @ 5748'. CIRC CSG W/2% KCL. TEST RBP & CSG TO 500#-30 MIN-OK. REL RBP & TOH. RAN 3 7/16" BP ON TBG TO 6288'.
3-13-98: LD HYD REL. TIH W/2 3/8" TBG.
3-14-98: TIH W/STRADDLE PKR 5934-6036'. TP @ 6288'. SPOT 20 BBLS 15% HCL ACID FLSH W/3 BW. PULL PKR TO 5900-6002'. INFLACE PKRS TO 500#. TIH W/PKR, SN & 2 3/8" TBG TO 1400'.
3-15-98: TIH W/7" PKR TO 5694'. SET PKR & ATT TO TEST BKSIDE. TIH W/7" PKR TO 5694'. SET PKR & LOAD & TEST-OK.
3-18-98: REL PKR. TIH W/PROD TBG.
3-20-98: TOH W/TBG. CHANGE RAMS IN BOP. TIH W/MOTOR, GAS SEPERATOR, PUMP, TBG SUB, TBG. TEST TBG TO 5000#. NDBOP. NUWH. INSTL FLOWLINE. WELL PUMPING @ 4:40 PM. RIG DOWN.
3-25-98: ON 24 HR OPT. PUMPED 22 BO, 1073 BW, & 1 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 4/29/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY _____ TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: