

Submit 3 Copies To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240

District II
811 South First, Artesia, NM 88210

District III
1000 Rio Brazos Rd., Aztec, NM 87410

District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-21756
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator LEA COUNTY PRODUCTION, LLC		6. State Oil & Gas Lease No. 63404-00
3. Address of Operator 7915 N. LLEWELYN, HOBBS, NM 88242		7. Lease Name or Unit Agreement Name: SARAH SUE
4. Well Location Unit Letter <u>D</u> : <u>660</u> feet from the <u>NORTH</u> line and <u>660</u> feet from the <u>WEST</u> line Section <u>36</u> Township <u>19S</u> Range <u>34E</u> NMPM <u>LEA</u> County		8. Well No. <u>3</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3718 GR		9. Pool name or Wildcat PEARL QUEEN

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation

TD 5137, PBD 5111, PERFS 4763-4996

MIRU INSTALL BOP, POH w/TBG, RUN RBP @4700', TEST CSG, SET PKR AND SWABB LOWER QUEEN(If SWABB DRY-ACIDIZE), SET RBP @4700', RUN CBL, PERFORATE UPPER QUEEN 4626-36, 4639-43, 4663-70 w/ 1 JSPF, SET PKR @4600', ACIDIZE PERFS 4626-4670 w/ 1000 GAL 15% NE FE, SWABB TEST FOR FLUID ENTRY.

(DEPENDING ON SWABB RESULTS WE MAY FRAC UPPER QUEEN)

GIH w/PRODUCTION EQUIPMENT AND RETURN TO PRODUCTION

WE PLAN TO START WORK AS SOON AS A PULLING UNIT IS AVAILABLE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Cogburn TITLE OPERATION COORDINATOR DATE 07-18-00

Type or print name JAMES COGBURN
(This space for State use)

Telephone No. (505)392-7095

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

