

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-2245	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	Central Vacuum Unit
3. Address of Operator	8. Farm or Lease Name
TEXACO Inc.	Central Vacuum Unit
4. Location of Well	9. Well No.
P. O. Box 728, Hobbs, New Mexico 88240	19
UNIT LETTER <u>K</u> <u>1750</u> FEET FROM THE <u>West</u> LINE AND <u>1650</u> FEET FROM	10. Field and Pool, or Wildcat
THE <u>South</u> LINE, SECTION <u>30</u> TOWNSHIP <u>17-S</u> RANGE <u>35-E</u> NMPM.	Vacuum Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3986' (GR)	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Rigged up. Pull rods & pump. Install BOP. Pull tubing.
2. Clean out to 4722' (PBTD).
3. Perforate 5 1/2" Csg W/22-JSPF @ 4611', 41,44,51,56,58, 61,66,69,73,76, & 4680'.
4. Set pkr. @ 4582'. Acidize W/5000 gals. 20% NEFE Acid. in 3-stages using 300# Benzoic Acid flakes & 100# rock salt between stages. Flush W/50 Bols. 2% CaCl Water.
5. Install production equipment. Test & place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Seay TITLE Asst. Dist. Mgr. DATE 7-7-83

ORIGINAL SIGNED BY EDDIE SEAY
APPROVED BY OIL & GAS INSPECTOR TITLE _____ DATE JUL 12 1983
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 11 1983

O.C.D.
HOBBS OFFICE