

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instruction re-
verse side)Form approved.
Budget Bureau No. 42-R1424.5. LEASE DESIGNATION AND SERIAL NO.
LC 061,598

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen, or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ XX Water Injection Well	7. UNIT AGREEMENT NAME Pearshall Queen Sand Unit
2. NAME OF OPERATOR Anadarko Production Company	8. FARM OR LEASE NAME Tract No. 8
3. ADDRESS OF OPERATOR 1014 West Avenue K Lovington, New Mexico	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL, 660' FSL Sec. 5, T 18 S, R 32 E, Lea County, New Mexico	10. FIELD AND POOL, OR WILDCAT Pearshall Queen
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5, T 18 S, R 32 E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3826 GL	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☒ XX
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled to 3800' TD, Mud vis 38, 16 cc WL, Ann GB-Densilog-Caliper. Wire line
cores 3706-11 and 3716-21. Porosity Ave 8%, no stain or odor. Intend to plug
and abandon well as follows: 25 sack plugs placed at 3685 (top Queen)
2400 (Top Base salt) 1100 (Top salt) 325 (base surface casing) Plugs will
extend upward approx. 100' from indicated depths. A 10 sack plug and marker
will be placed at the surface. Plugging operation will take place 26 August 1967.

18. I hereby certify that the foregoing is true and correct.

SIGNED

Donald R. Layton

(This space for Federal or State office use)

TITLE

District SuperintendentDATE **27 August 1967**

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
DATE**AUG 30 1967****J. L. GORDON**
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.