

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG 1049	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A	7. Unit Agreement Name
2. Name of Operator Elk Oil Company	8. Farm or Lease Name State KA
3. Address of Operator P. O. Box 310, Roswell, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER O 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 17S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3841 GL	12. County Lea

16.

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

A TD of 9653 was reached on 9-10-67 after DST's failed to prove any oil or gas production on 9-12-67 we asked for approval to plug and abandon. We plan to place cement plugs as follows:

25 sx @ TD 9653  
25 sx @ 6900 Tubb  
25 sx @ 6000 base SA  
25 sx @ 5200 top SA  
25 sx @ 4400 base of 8 5/8  
shoot off free 8 5/8 and fill annulus w/mud  
25 sx in 8 5/8 stub; 25 sx top of salt - 2100  
25 sx base of surface - 350; 10 sx @ surface w/4"x4" marker  
Location will be cleaned up and restored to the original contour.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K.D. McPeters K.D. McPeters, Agent DATE 9-12-67

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: