

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 24 11 29 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
----------------------------	--

5. State Oil & Gas Lease No.	OG-1635
------------------------------	---------

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator MONSANTO COMPANY	8. Farm or Lease Name DON STATE
3. Address of Operator 101 North Marienfeld, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 19S RANGE 34E NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) RKB 3809'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-2-68: Set Baker bridge plug at 9900' in 4½" casing w/1 sk cement on top.
7-7-68: Shot 4½" casing at 9011' and pulled.
7-9-68: Spotted cement plugs as follows: 25 sx @ 9011', 25 sx @ 7960', 25 sx @ 6280',
25 sx @ 4930', 25 sx @ 4605', 25 sx @ 4125'.
7-10-68: Shot 8-5/8" casing at 1670' and pulled.
7-11-68: Spotted 25 sx cement plug at 1660' and 25 sx at 430' in 11-3/4" casing. Set
bridge at 10' and cemented to surface with 10 sx. Set 4" marker in top
extending 4' above GL with location marked thereon.

You will be advised when location has been cleaned up and ready for final inspection.

Hole was filled w/9.4# mud between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. W. Wood</u>	TITLE <u>Dist. Prod. Supt.</u>	DATE <u>7-23-68</u>
APPROVED BY <u>John W. Rungan</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		