

COPIES RECEIVED	
DISTRIBUTION	
STATE	
FEDERAL	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISS.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
OG-2001

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- Dry Hole
Name of Operator
Read & Stevens, Inc.
Address of Operator
P. O. Box 1518, Roswell, NM 88201
Location of Well
UNIT LETTER I 1830 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 11 TOWNSHIP 19-S RANGE 34-E N.M.P.M.

7. Unit Agreement Name
--
8. Farm or Lease Name
Quail State
9. Well No.
3
10. Field and Pool, or Wildcat
Quail Queen
12. County
Lea

11. Elevation (Show whether DF, RT, GR, etc.)
3960' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

Describe proposed or completed operations (clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 1-30-79, received verbal approval from Mr. Jerry Sexton, OCC, Hobbs, New Mexico, to plug and abandon as follows:

1. Lay down drill collars and run tubing to top of 8 5/8" casing. Hole full of good mud.
2. Set 75 sx. cement plug 1020'-920'.
3. Set 90 sx. cement plug 400'-300'.
4. Set 10 sx. cement plug 10' to surface.
5. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John L. Anderson Jr. TITLE Agent DATE 2-12-79

APPROVED BY Jerry Sexton TITLE Dist 1, Supv DATE FEB 1 1979