(May 1963)	' 'ITED STATES SUBMIT IN THE ICATE	For		
	DEPARTMENT OF THE INTERIOR (Other Instruction of the Control of th	Budget Bureau No. 42-R1424.		
	GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND SERIAL NO.		
SII	NDRY NOTICES AND REPORTS ON WELLS	N. M. 05519 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
(Do not use th	is form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT— for such proposals.)			
OIL Y GAS		7. UNIT AGREEMENT NAME		
. NAME OF OPERATOR	U OTHER	Mescalero Ridge		
Ernes	t A. Hanson	8. FARM OR LEASE NAME W2		
. ADDRESS OF OPERAT		Mescalero Ridge Un		
P. O.	Box 1515, Roswell, New Mexico	8		
See also space 17 b	Report location clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT		
At surface	1980' FSL & 990' FWL	Pearl Queen		
	Sec. 26, T-19-S, R-34-E, N.M.P.M. Lea County, New Mexico	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
4. PERMIT NO.	15 Presidence (Ch.	Sec. 26 - 195 - 341		
	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE		
8 .	3755° KB	Lea N. Mex.		
TEST WATER SHUT-		QUENT REPORT OF:		
FRACTURE TREAT	PULL OR ALTER CASING WATER SHUT-OFF MULTIPLE COMPLETE	REPAIRING WELL		
SHOOT OR ACIDIZE	ABANDONS	ALTERING CASING		
REPAIR WELL	CHANGE PLANS (Other)	ABANDONMENT*		
(Other)	(Norm: Report result	s of multiple completion on Well pletion Report and Log form.)		
DESCRIBE PROPOSED (proposed work. I nent to this work.)	R COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates f well is directionally drilled, give subsurface locations and measured and true vertice.	, including estimated date of starting any ai depths for all markers and sones perti-		
3- 1-68	Commence drilling. T.D. 224' red beds. J-55 casing @ 224' w/200 sx. reg. + 2% Cacirculated to the surface.	Ran 8-5/8", 24#, aCl. Cement		
		· ·		
2 2 60	u o a ob .			
3- 2-68	W.O.C. 24 hours. Pressure tested casing 30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for		
	30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for lead.		
3- 2-68 3-14-68	W.O.C. 24 hours. Pressure tested casing 30 minutes. No leaks. Prep. to drill ah T.D. 5035' dolomite. Running logs.	to 600 lbs. for mead.		
	30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for lead.		
	30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for sead.		
	30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for lead.		
	30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for lead.		
	30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for mead.		
	30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for lead.		
_	30 minutes. No leaks. Prep. to drill ah	to 600 lbs. for lead.		

18. I hereby certify that the foregoing is true and correct		<u> </u>			
SIGNED Hany F. Schman	TITLE Exploration	Manager	DATE Ma	r. 15.	1968
(This space for Federal or State office use)					
APPROVED BY	TITLE	APPROVE		4.	
CONDITIONS OF APPROVAL, IF ANY:			DATE		
		MAD 1935	$\Omega : \mathbb{R}^n \to \mathbb{R}^n$		