NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old ;
SANTA FE	NEW MEXICO OIL CON:	SERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			Fuective 1-1-02 -
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE	_		State X Fee
OPERATOR			5. State Oil & Gas Lease No.
			OG-3813
SUNDR	RY NOTICES AND REPORTS ON	IWELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. 1. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
**			7. Unit Agreement Name
WELL WELL	OTHER-		_
2. Name of Operator			8. Farm or Lease Name
Charles B. Read			!
3. Address of Operator			Mobil 9. Well No.
P. O. Box 2126, Roswell, New Mexico 88201			1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER E 1	1980 FEET FROM THE North	660	Quail Queen
ONTI DELITER	FEET FROM THE	LINE AND FEET FF	TOM CHAIL SHEEL
THE West LINE, SECTION 13 TOWNSHIP 19S RANGE 34E NMPM.			
LINE, SECTION	JN TOWNSHIP	RANGENM	PM (
	15. Elevation (Show whether	DF. RT. GR. etc.)	12, County
	3943' GL	er, m, on, ever,	, , , , , , , , , , , , , , , , , , , ,
16. Charle			Lea
NOTICE OF IN	Appropriate Box To Indicate N		
NOTICE OF IN	TENTION TO:	SUBSEQUE	NT REPORT OF:
DED S S S S S S S S S S	•		
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	-
07.115	<u></u>	OTHER	
OTHER			
17. Describe Proposed or Completed Op	perations (Clearly state all pertinent det	rile and give portions down in the	ing estimated date of starting any propose
work) SEE RULE 1103.	description and personal description	s, and give periment dates, includi	ng estimated date of starting any propose
To place to show done	3 3 -4 - 3		
To plug & abandon d	repreted oil well		
		•	
To set 50 sx plug @			
To cut $4\frac{1}{2}$ " csg @ 20	50¹		
To pull $4\frac{1}{2}$ " csg			
To set 35 sx plug @	2108! - 2008!		
To set 35 sx plug @			
To set 35 sx plug @			
To set 10 sx plug @	•		
And erect dry hole :	marker		
		•	
		•	
10 7 10-11			
to. I nereby certify that the information	above is true and complete to the best of	f my knowledge and belief.	
bedu me ktt	/		
SIGNED WHILE THE		Agent	PATE 9/11/70
1/20 # 1			
APPROVED BY	Chinin TITLE	PERVISOR DEFINCE	_ DATE SEP 18 1370
77 \		- , 	DATE_ULF 4 10/1

CONDITIONS OF APPROVAL, IF ANY

RECEIVED

SEP 17 1970

OIL CONSERVATION COMM.
HOBBS. N. M.