

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-025-22984

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

VB-0220

7. Lease Name or Unit Agreement Name

Bush State

8. Well No.

1

9. Pool name or Wildcat

Scharb Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Manzano Oil Corporation 505/623-1996

3. Address of Operator

P.O. Box 2107/Roswell, NM 88202-2107

4. Well Location

Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section 12 Township 19 South Range 34 East NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3945' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/08/95 MIRU WL w/5-1/2" CIBP. RIH & set @ 9400'. RU pump & circ 200 bbls MLF. M&P 25 sks C1 "C" cmt 9400-9154'. M&P 20 sks 7071-6874'. M&P 20 sks C1 "C" cmt 5123-4976'. M&P 20 sks C1 "C" cmt 4054-3857'.
8/09/95 Cut csg @ 1500'. RU csg equip & POOH w/csg string.
8/10/95 RIH w/tbg open ended to 1550'. M&P 50 sks C1 "C" cmt. WOC & tag TOC @ 1331'. 50 sks 1550-1327'. PUH to 900'. M&P 150 sks C1 "C" cmt. Squeeze 50 sks & leave 100 in 8-5/8" csg. PUH. WOC & tag TOC @ 523'. PUH to 60'. M&P 15 sks 60' to surface. Cut off WH. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Allison Hernandez

TITLE

Engineering Tech.

DATE 11/09/95

TYPE OR PRINT NAME

Allison Hernandez

TELEPHONE NO. 505/623-1996

(This space for State Use)

ORIGINAL SIGNED BY
JOHN R. HERNANDEZ
CHIEF OF DIVISION

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 17 1995