(May 1963)		NIT D STATE		SUBMIT IN TRIE (Other instruction verse side)	PL* °E* as re-	5. LEASE DESIGNAT	Bureau No. 42-R142 FION AND SERIAL NO.
	GE	OLOGICAL SU	RVEY			NM 052	
SUN (Do not use this	DRY NOTIC	LES AND REP Is to drill or to deeper ION FOR PERMIT-	PORTS ON	WELLS to a different reserv	oir.	6. IF INDIAN, ALLC	DTTEE OR TRIBE NAM
1. OIL GAS WELL X WELL	OTHER			······································		7. UNIT AGREEMEN	TNAME
2. NAME OF OPERATOR	<u>. </u>	nzoil United	Inc.			8. FARM OR LEASE Mescalero	NAME D Ridge Unit
3. ADDRESS OF OPERATOR	2	r 1828 - Mid		as 79701		9. WELL NO.	
4. LOCATION OF WELL (R See also space 17 belo At surface	(eport location clea ow.)	arly and in accordance	ce with any Sta	te requirements.*		10. FIELD AND POO Lea 11. sec., t., r., m., M.,	
554' FEL	. & 554' FS	L of Section	35, T-19	-S, R-34-E		SURVEY OR	T-19-S, <u>R-3</u>
14. PERMIT NO.		15. ELEVATIONS (Show	w whether DF, RT, 00.5 GL	GR, etc.)		12. COUNTY OB PA	ARISH 13. STATE
16.	Check Apr	propriate Box To I	Indicate Nati	ure of Notice, Re	port, or O)ther Data	
,	NOTICE OF INTENT:		1			ENT REPORT OF:	
TEST WATER SHUT-0		ULL OR ALTER CASING		WATER SHUT-OFF		REPAIR	ING WELL
FRACTURE TREAT		ULTIPLE COMPLETE		FRACTURE TREAT	MENT	ALTERI	NG CASING
SHOOT OR ACIDIZE	AI	BANDON*		, SHOOTING OR ACI	DIZING X	ABANDO	ONMENT*
REPAIR WELL	CI	HANGE PLANS		(Other)			Atom Wall
(Other) 17. DESCRIBE PROPOSED OF				Completion	or Recompl	of multiple comple etion Report and Lo	og form.)
nent to this work.)				s and measured and			
6-10-70	Spotted 2 Ran Corre Ran tubin runs & we	200 gallons a elation log & ng & packer. ell kicked of cential test.	cetic aci perforat - Break d f flowing	d over inter ed 9611-9636 own perforat	val to '. (9 h	oles).	- <u>-</u>
	Spotted 2 Ran Corre Ran tubin runs & we Start pot	elation log & ng & packer. ell kicked of cential test.	cetic aci perforat - Break d f flowing	d over inter ed 9611-9636 own perforat	val to '. (9 h ions -	oles).	
6-10-70 18. I hereby cerefy tha	Spotted 2 Ran Corre Ran tubin runs & we Start pot	true and correct	cetic aci perforat - Break d f flowing	d over inter ed 9611-9636 own perforat	val to '. (9 h ions -	Date	ab $-6-12-70$
6-10-70 18. I bereby certify that SIGNED	Spotted 2 Ran Corre Ran tubin runs & we Start pot	true and correct	cetic aci perforat - Break d f flowing	d over inter ed 9611-9636 own perforat	val to '. (9 h ions -	Date	ab $-6-12-70$

JUN 23 1970 OIL CONSERVATION COMM. HOBBS, N. M.

RECEIVED

~

•