

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
North Vac. Abo Unit	
9. Well No.	
151	
10. Field and Pool, or Wildcat	
North Vac. Abo	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- **WIW**

2. Name of Operator
Mobil Oil Corporation

3. Address of Operator
Box 633, Midland, TX 79701

4. Location of Well
UNIT LETTER **F** **2130** FEET FROM THE **West** LINE AND **1980** FEET FROM
THE **North** LINE, SECTION **23** TOWNSHIP **17-S** RANGE **34-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
4030 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NORTH VACUUM ABO UT #151, 9460 PBTD.

-17 Bled off TP, instl BOP, POH w/ 2-3/8 Buttress tbg & Baker seal assembly, change rams in BOP, run 7" ret BP on 2-7/8 tbg set in 7" liner @ 4500, spotted 5x of sd on plug, Howco displ hole w/ 16# mud.

-20 Ran BOT nose guide on 121 jts 7" OD 26.0# & 23.0# N80 & J55 8rd LT&C csg set in top of 7" liner @ 4259, Howco cmtd csg w/ 900x Class H cmt containing .05% CFR2 + .4# salt + 1/4# flocele/x, job compl @ 10 pm 1/18/75, SI & SD, WOC. 18 hrs.

-21 Remove BOP, NU 7" csg, instl BOP, ran 6-1/8 bit on 4 - 4 1/2 DC's & 2-7/8 tbg, drill cmt from 4197-4203, drill on wiper plug 30 min.

-22 Drill plug & cmt from 4203-4265, ran bit to 4450, test csg w/ 1500#/15 min/ok, wash sd off BP @ 4500, POH, LD DC's, SDFN.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Authorized Agent DATE 1-31-75

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: