

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO. 30-025-23690
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-6005
7. Lease Name or Unit Agreement Name State "36"
8. Well No. 2
9. Pool name or Wildcat Lea Bone Springs
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3707 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS).

1. Type Of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Mack Energy Corporation
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960
4. Well Location Unit Letter <u>L</u> : <u>2130</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>19S</u> Range <u>34E</u> NMPM <u>Lea, NM</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3707 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/23/2002 Spot 40 sx plug @ 4060'.
10/24/2002 Tag plug @ 3928', spot 35 sx plug @ 3420', spot 35 sx. plug @ 1930', spot 35 sx plug @ 400', WOC tag @ 270', spot 10 sx surface plug @ 60.
10/29/2002 Cut off wellhead and install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Crissa D. Carter TITLE Production Analyst DATE 10/30/02

TYPE OR PRINT NAME Crissa D. Carter TELEPHONE NO. 748-1288

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 11-27-02

CONDITIONS OF APPROVAL, IF ANY:

GWW