STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	T	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 2088	Form C-103 Revised 10-1-78
SANTAFE	SANTA FE, NEW MEXICO 87501	K641260 10-1-10
FILE		5a. Indicate Type of Lease
U.S.O.S.		
LAND OFFICE		
OPERATOR		5, State Oll & Gas Lease No.
		E-3454
SUNDRY NO	TICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSAL:	OTICES AND REPORTS ON WELLS 5 TO DRILL ON TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. 6 FERMIT—11 FERMI C-1011 FOR SUCH PROPODALS.1	
1.		7, Unit Agreement Name
01L		1
	THE#-	8. Farm or Lease Name
2. Name of Operator		
GULF OIL CORPORATION	N	Lea "DS" State
3. Address of Operator		9. Well No.
P. O. Box 670, Hobbs	s, NM 88240	2
4. Location of Well		10. Field and Pool, or Wildcat
n . 770	PEET FROM THE North LINE AND 560 FEET FROM	Bone Springs
UNIT LETTERD	PEET FROM THE HOLET LINE AND DOO FEET FROM	rrrrititititititititi
	2/7	
THE West LINE, SECTION	36 TOWNSHIP 198 NANGE 34E NMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3723' GL	Lea
it. Charle Appe	opriate Box To Indicate Nature of Notice, Report or Otl	ier Data
	•	
NOTICE OF INTEN	TION TO: SUBSEQUENT	REPORT OF:
,		<u></u>
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT 🗶
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
The state of the s	OTHER	
OTHER		
12 Describe Proposed or Completed Operatio	ns (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.		
_	7/2721	root a ric
9770' TD Spot 10 sx cmt	f/9350' up to 9300'; spot 20 sx cmt f/5400' u	p to 5300'; Cut 5室'
csg @ 2327'. Got permiss	ion from Mr. Saxton w/OCD to pmp cmt plug f/2	358' up to 2210'.
Cut 8-5/8" csg @ 990'. S	pot 20 sx cmt f/2160' up to 2100'. Pull up h	ole & spot 35 sx cmt
f/1950' up to 1850'. Pul	1 up hole & spot 70 sx cmt f/1040' up to 940'	• GIH $w/2-7/8^{11}$ tbg.
tag cmt @ 912'. Spot 80	sx cmt @ 400'. WOC 4½ hrs, tag cmt @ 367'.	Spotted 55 sx cmt.
	sx cmt 30' f/surf up to surf. Install dry ho	le marker Cleaned
-		· Hanrey Greama
& cleared loc. P & A com	plete 3-27-80.	
		R.
• *		•
		•
		•
	1	
13. I hereby certify that the information above	is true and complete to the best of my knowledge and belief.	
a		
$II = II \otimes XV \otimes A$	A. Aren Dundanan	3~31~80
*10HED 11-12- XVXXX	Area Engineer	00-10-0
		2000 0 0 0000
a Y		D: 5 5 6 7 7 1 7 7 1 1 1 1 1 1 1