

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> WELL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator	5. State Oil & Gas Lease No. <b>X</b>
3. Address of Operator <b>Texaco Inc.</b>	7. Unit Agreement Name <b>E-1722-1</b>
4. Location of Well <b>P. O. Box 728 Hobbs, New Mexico 88240</b>	8. Farm or Lease Name
UNIT LETTER <b>D</b> FEET FROM THE <b>980</b> LINE AND <b>North</b> FEET FROM <b>913</b>	9. Well No. <b>New Mexico "N"</b>
THE <b>West</b> LINE, SECTION <b>30</b> TOWNSHIP <b>17 S</b> RANGE <b>35 E</b> NMPM.	10. Field and Pool, or Wildcat <b>9</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Vacuum Clorteta</b>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Ran CIBP in 4 1/2" csg & set @ 6074'.
2. Dumped 3 sx cmt top of CIBP.
3. Cut 4 1/2" csg @ 2671'. Rec 85 jts 4 1/2" csg.
4. Ran tbq & displd w/mud.
5. Spot 35 sx cmt plug 2690-2590; 35 sx cmt plug 1650-1560', & 35 cmt plug 100' to surface.
6. Install marker & clean location.
7. ASP (P&A) 8-24-74.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Nathan E. Regg* TITLE Asst. Dist. Supt. DATE August 27, 1974

APPROVED BY *Nathan E. Regg* TITLE  DATE JAN 1975

CONDITIONS OF APPROVAL, IF ANY: