

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002523880
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	857947
7. Lease Name or Unit Agreement Name	NORTH VACUUM ABO WEST UNIT
8. Well No.	19
9. Pool Name or Wildcat	VACUUM ABO, NORTH
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4062' RKB

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>J</u> : <u>2104</u> Feet From The <u>SOUTH</u> Line and <u>1856</u> Feet From The <u>EAST</u> Line Section <u>28</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4062' RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPERATION ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☒ Repair water flow

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-10-99: MIRU. UNSEAT PUMP.
9-11-99: NDWH. NUBOP. REL TAC. TIH W/BIT, CSG SCRAPER, 2 7/8" TBG TO 3583'. TIH W/RBP, & TBG. SET RBP @ 3514'. CIRC HLE W/2% KCL. TEST RBP TO 500 PSI-OK. SPOT 2 SX 12/20 SX ON RBP.
9-13-99: TIH W/PKR, SN, & TBG TO 1558'. SET PKR. TIH W/PERF GUN. PERF 4 HLES @ 1700'. RU REV EQPT. CIRC CSG @ 300 PSI. REL PKR. TIH W/CMT RET, & TBG TO 1600'. PUMP THRU RET. SET RET. TEST TBG TO 2000 PSI.
9-14-99: PRESS CSG TO 500#. MIX & PUMP 500 SX CL C W/2% CACL.
9-15-99: TIH W/BIT, & DC'S ON TBG. TAG @ 1592'. DRILL CMT 1592-1600'. DRILL CMT RET 1600-02'. DRILL HARD CMT 1602-1693'.
9-16-99: DRILL CMT 1693-1746'. TEST TO 300#-30 MINS. WASH SAND OFF RBP @ 3514'. TIH W/RET TOOL ON TBG TO RBP @ 3514'. REL RBP. TIH W/OPSMA, PERF SUB, SN, TBG, TAC.
9-17-99: NDBOP. SET TAC. NUWH. MA @ 8834'. SN @ 8798'. TAC @ 8596'. TIH W/GAS ANCHOR, PUMP, SNKR BARS & RDS. HANG ON. LOAD & TEST W/45 BW TO 500#-OK. RIG DOWN.
9-19-99: ON 24 HR OPT. PUMPED 14 BO, 1 BW, & 7 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 09/21/1999

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR
APPROVED BY _____ DATE SEP 20 1999
CONDITIONS OF APPROVAL, IF ANY:

JC