

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24026
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	7. Lease Name or Unit Agreement Name Ritts State
2. Name of Operator Chevron U.S.A. Inc.	8. Well No. 2
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Pool name or Wildcat Vacuum Grayburg/San Andres
4. Well Location Unit Letter <u>H</u> : <u>2080</u> Feet From The <u>North</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>21</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>Lea</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4058'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Abandon GB/SA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed: 5-3-89 thru 5-8-89

TD: 8960 PB: 8893

Note: Squeezed off Grayburg-San Andres zone and turned wellbore over to Texaco.

POOH w/production equip. Set CIGR at 4436'. Batch mix 150sx. Sqz well and reverse out 13bbbls cmt. WOC 20 hrs. DO CIGR and cmt to 4519'. Cmt green, shut down over nite. Circulate hole. Drlg cmt to 4735'. Circ. hole. Tst csg to 500psi, stop surface leaks. TIH to 4756. Wash sand off RBP and engage RBP. Release RBP. LD WS. ND BOP & NUWH. RD Unit. Turn over to production dept, Texaco.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akim TITLE Staff Drilling Engineer DATE 5-10-89
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 11 1989

2A 8818A

E

RECEIVED

MAY 10 1949

OFF
HONORARY