

## U.S. CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |  |
|------------------------|--|--|
| NO. OF COPIES RECEIVED |  |  |
| DISTRIBUTION           |  |  |
| SANTA FE               |  |  |
| FILE                   |  |  |
| U.S.O.S.               |  |  |
| LAND OFFICE            |  |  |
| OPERATOR               |  |  |

|  |
|--|
| 5a. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br>B-3385   |

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|  |  |
|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   | 7. Unit Agreement Name                           |
| 2. Name of Operator<br>Gulf Oil Corporation  | 8. Farm or Lease Name<br>Ritts State             |
| 3. Address of Operator<br>P. O. Box 670, Hobbs, NM 88240   | 9. Well No.<br>2                                 |
| 4. Location of Well<br>UNIT LETTER <u>H</u> , <u>2080</u> FEET FROM THE <u>North</u> LINE AND <u>560</u> FEET FROM<br>THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>17S</u> RANGE <u>34E</u> NMPM. | 10. Field and Pool, or Wildcat<br>No. Vacuum Abo |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>4058' GL  | 12. County<br>Lea                                |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

|  |  |  |   |
|--|--|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>                            | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                                | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <u>Test SanAndres zone</u> <input checked="" type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Set RBP at 4800'. GIH with mud anchor, perf nipple, SN & tubing anchor catcher on 2-3/8" tubing; land tubing to position perf nipple at 4725'. GIH with pump and tapered rod string. Space out rods and hang on pumping unit. After well has stabilized, perform GOR test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED QD Ritts TITLE Area Engineer DATE 9-29-80APPROVED BY [Signature] TITLE [Signature] DATE SEP 30 1980

CONDITIONS OF APPROVAL, IF ANY: