	-	
NO. OF CUPILS RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE		Effective 1-1-65
U.J.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State XX Fee
OFERATOR	-	5. State Oil 6 Gas Lease No.
· · · · · · · · · · · · · · · · · · ·		L-3672
STRUCT		
(DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS TOPOSALS TO DRILL OR TO DELPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
1.	TION FOR FERMIT (FOPM C-101) FOR SUCK PLOPUSALS.)	
WELL XX VELL	OTHER.	7. Unit Agreement Name
2. Name of a stator	OTHER.	() [¹]
Mobil Oil Corporation	8. Farm or Lease Name	
3. Address of Creator	State LL	
Box 633, Midland, Tex	vac 70701	9. Well No.
4. Location of Well		1
	1700	10. Ffeld and Pool, or Wildeat
UNIT LETTER U	1780 FEET FROM THE South LINE AND 1980 FEET F	FROM Wac - Grayburg S.A.
		TENNIN IN ING I WALLEY I THE STATE IN INC.
THE East LINE, SECTI	10N 16 TOWNSHIP 17-S RANGE 34-E NN	MPM AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
TTO WITCHTTY TO THE	15. Elevation (Show whether DF, RT, GR, etc.)	
	12. County	
	4070 GR	Lea
¹⁶ . Check	Appropriate Box To Indicate Nature of Notice, Report or	Other Date
NOTICE OF H		ENT REPORT OF:
	30B3E.Q0F	ENT REPORT OF:
PERFORM REMEDIAL AORK	PLUG AND ABANDON REMEDIAL WORK	ſ
TEMPORARILY ABANDON		ALTERING CASING
PULL OF ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
		F1
OTHER	01 HER	
01115 X		
 Describe Proposed or Completed Op work) SEE RULE 1103. 	perations (Clearly state all pertinent details, and give pertinent dates, include	ding estimated date of starting any proposed
E 20 7E Dianation C		
5-20-75 Rigged up Se	elect Well Service pulled 2-3/8 EUE 8Rd tubing	- Western Wire Line Servio
Set UIDr V O	0000 - OUNDED IUSX CEMENT W/DIASS bottom baile	in SDEN
5-21-75 Ran 283 Jts	8Rd tubing tagged cement plug @ 8859 31'plug	circu hole with 9.5 brine a
riusx mua pu	ified tubing out of noie. SDEN	
5-22-75 Haliburton r	an CIBP on end of 2-3/8 8Rd tubing to 7750 ct	BD would not get

- 5-22-75 Haliburton ran CIBP on end of 2-3/8 8Rd tubing to 4750 CIBP would not set changed springs re-ran and set 0 4750 spotted 20 sx cement on top of CIBP Pulled up to 1777 spotted 50sx cement 110' plug pulled tubing. SDFN
 5-23-75 Spotted 10sx cement on top removed well head set P&A marker installed.

Lease inspected by NMOOC - P&A 5-23-75

15. I hereby certify that the internation above is true and complete strues Christine O. Sucker			DATE	5-30-75
man <u>M. Nastanico</u> Martinico	The state	OD & GALL CHECTER	un de le cale	FEB 191980