STATE UP NEW MEXICU ENERGY AND MINERALS DEPARTMENT

THE PART MINE THAT OF	CONT.	LIVIE
He of Corits Accelved		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.	1	
LAND OFFICE		
OPERATOR	1	i

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 Revised 10-1-75

FILE.	SANTA FE, NEW MEXICO 87501	7-C11360 10-1-7.
		5a, Indicate Type of Lease
U.S.G.S.		
LAND OFF		
OPERATOR		5. State Oll & Gas Lease No.
	API NO. 30-025-24061	B-4118
	SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT U	USE THIS FORM FOR PROPOSALS TO DRILL OR TO OCCPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" FORM C-101) FOR SUCH PROPOSALS.)	
[1.	TOTAL C-TOTI FOR SUCH PROPOSALS.	
OIL X	GAB [TT]	7. Unit Agreement Name
<u></u>	WELL OTHER-	
2. Name of Operate	or ————————————————————————————————————	8. Farm of Lease Name
Phillips	T	
3, Address of Oper	9. Weil No.	
Room 401	3, 401, 110.	
Room 401	25	
		10. Field and Pool, or Wildon
UNIT LETTER _	J 2120 FEET FROM THE South LINE AND 1840 FEET FR	Vacuum, North Abo
	FLET PR	THITTI THE THE THE
Fa	ost 21 17.0	
THE LICE	IST LINE, SECTION 21 TOWNSHIP 17-S RANGE 34-E NMF	··· //////////////////////////////////
]_(
1111111111	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4061' GR 3969' RKB	
16.		Lea (\)\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	Check Appropriate Box To Indicate Nature of Notice, Report or (Other Data
	NOTICE OF INTENTION TO: SUBSEQUE	NT REPORT OF:
PERFORM REMEDIAL	L WORK PLUG AND ASANDON REMEDIAL WORK	
TEMPORARILY ABAN		ALTERING CASING
	Commence Diliting Opins.	PLUG AND ABANDONMENT
PULL OR ALTER CAS		
	OTHER Perforate casi	ing and squeeze X
OTHER	cement per OCD	request
17, Cercribe Propo work) SEE RU	oned or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi	ng estimated date of starting any proposed
worky see no		
6-11-80	MI Well Service Unit. Pulled rods and tbg. Set BP at 35	50' Dumped 3 sys
	sand. Perfd 5-1/2" csg at 1675'4 holes. Set ret at 15	50! Cmt 4 == 1400
	SXS Cl "C" W/2% CaClo Flohd w/5 PM Closed water	30 . Circa W/ 400
	sxs Cl "C" w/2% CaCl ₂ . Flshd w/5 BW. Closed valve and s sxs. Reversed out 2 sxs. WOC 16 hrs.	qzd formation w/165
	sxs. Reversed out 2 sxs. WOC 16 hrs.	
(10 00		
6-12-80	Drld ret at 1564'. Drld cmt at 1575'.	
6-13-80	Drld cmt at 1680'. Pressd csg to 1500#, OK. Pulled bit,	
	tbg at 8853'. Set 2" x 1-1/4" x 20' pmp at 8852'.	set 290 jts 2-3/8"
	cog at 60033: Set 2 x 1-1/4 x 20 pmp at 8852.	•
6 16 00		•
6-16-80	Single in Abo formation and return to production.	
	•	
10. I hereby certify	that the information above is true and complete to the best of my knowledge and belief.	
(1) / Y.	11	
XI	9 . 1 W 1 W 11	
HENCO TO	Sr. Engineering Specialist	June 18, 1980
		REER! O (1 TION)
	Side Signed St	1110 S 3 1200